





Class TN 530

Book : M 63

Copyright N<sup>o</sup> \_\_\_\_\_

**COPYRIGHT DEPOSIT.**













A

# MANUAL OF ASSAYING:

*THE FIRE ASSAY OF GOLD, SILVER, AND  
LEAD, INCLUDING AMALGAMATION  
AND CHLORINATION TESTS.*

BY  
ALFRED STANLEY MILLER,  
*Professor of Mining and Metallurgy,  
University of Idaho.*

*SECOND EDITION, REVISED AND ENLARGED.*

FIRST THOUSAND.

THE LIBRARY

OF CONGRESS

NEW YORK:

JOHN WILEY & SONS.

LONDON: CHAPMAN & HALL, LIMITED.

1901.



TN 550

. 1765

THE LIBRARY OF  
CONGRESS,  
TWO COPIES RECEIVED  
MAR 26 1902  
COPYRIGHT ENTRY  
Aug 27-1901  
CLASS a XXc NO.  
15761  
COPY B.

Copyright, 1900, 1901,

BY

ALFRED STANLEY MILLER

ALFRED STANLEY MILLER

ALFRED STANLEY MILLER

ROBERT DRUMMOND, PRINTER, NEW YORK.

2-9816

## PREFACE.

---

The plan of this book is a departure from the books on this subject with which the writer is familiar. The apparatus is brought in where its use is easily understood. The student is taught the operations of the fire-assay by practising with an ore easy to assay. He is then better prepared to understand the directions for assaying more complex ores.

The writer's experience in teaching this subject has convinced him that there is room for a book of this kind.

The following books have been consulted in the preparation of this book:

Aaron's Assaying; Ricketts and Miller's Notes on Assaying; Hiorns's Practical Metallurgy and Assaying; Furman's Manual of Assaying; Brown's Manual of Assaying; Beringer's Assaying; and Rose's Metallurgy of Gold.

The crucible charges from Ricketts and Miller's Notes on Assaying, and the crucible and scorification charges from Furman's Manual of Practical Assaying are quoted by permission of the authors.

June, 1900.



## PREFACE TO THE SECOND EDITION.

---

IN this edition the chapter on slags has been enlarged, and the following subjects have been added: The assay of ore containing coarse metal, the assay of copper ores and copper-bearing materials for gold and silver, the dry assay of mercury, the cyanide method and the iodide method for the determination of copper, and the ammonium molybdate method for the determination of lead.

MOSCOW, IDAHO, March, 1901.



# CONTENTS.

---

|  | PAGE |
|--|------|
| CHAPTER I.                                   |      |
| Cupels and Flux.....                         | 1    |
| CHAPTER II.                                  |      |
| Assay of Ores.....                           | 5    |
| CHAPTER III.                                 |      |
| Notes on the Assay of Ores.....              | 29   |
| CHAPTER IV.                                  |      |
| Fluxes and Reagents.....                     | 47   |
| CHAPTER V.                                   |      |
| Slags.....                                   | 55   |
| CHAPTER VI.                                  |      |
| The Assay of So-called Refractory Ores ..... | 61   |
| CHAPTER VII.                                 |      |
| Amalgamation and Chlorination Tests.....     | 82   |



## CHAPTER VIII.

|  | PAGE |
|--|------|
| The Assay of Ore containing Coarse Metal . . . . . | 88   |

## CHAPTER IX.

|  |    |
|--|----|
| The Assay of Copper Ores and Copper-bearing Materials<br>for Gold and Silver . . . . . | 91 |
|--|----|

## CHAPTER X.

|                                    |     |
|------------------------------------|-----|
| The Dry Assay of Mercury . . . . . | 100 |
|------------------------------------|-----|

## CHAPTER XI.

|  |     |
|--|-----|
| Volumetric Determination of Copper . . . . . | 108 |
|--|-----|

## CHAPTER XII.

|  |     |
|--|-----|
| Volumetric Determination of Lead . . . . . | 124 |
|--|-----|

## APPENDIX A.

|  |     |
|--|-----|
| Supplementary Notes on the Assay of Ores . . . . . | 128 |
|--|-----|

## APPENDIX B.

|                  |     |
|------------------|-----|
| Tables . . . . . | 136 |
|------------------|-----|

# A MANUAL OF ASSAYING.

---

## CHAPTER I.

### CUPELS AND FLUX.

#### 1. To Make Cupels.

Take a miner's pan (Fig. 1) full of bone-ashes and pass them through a 40-mesh sieve, moisten sufficiently to make them cohere



FIG. 1.

slightly, like flour when compressed in the hand (about 1 oz. of water to a pound of bone-ashes). Work them between the hands until the moisture is evenly distributed.

Place a 1½-inch cupel mould (Fig. 2) on a smooth iron plate or anvil, fill it with the moistened bone-ashes, and drive the die down by a number of light blows with a mallet (Fig. 3), turning the die after each blow.



FIG. 2.




FIG. 3.

Move the mould on the iron plate so as to give the cupel an even base, then turn the mould and die upside down, and push the cupel out with the die. Turn cupel when taking it off. Place the cupels on a dry board, and dry them slowly and carefully in a warm room.



Too much water makes the cupels less porous, and if too little water is used, they will crumble. If the cupels stick in the mould, the bone-ashes are too dry or they are compressed too hard. Cupels should be made several weeks before they are used. At the Royal Mint the cupels are made two years before they are used.

**2. Flux for Ordinary Silicious (Quartz) Gold and Silver Ores.**

|   |     |       |
|---|-----|-------|
| Litharge, PbO . . . . .                             | 100 | parts |
| Bicarbonate of sodium, HNaCO <sub>3</sub> . . . . . | 100 | “     |
| Wheat flour . . . . .                               | 4   | “     |

Spread a rubber or an oil cloth on the mixing-table. Weigh out 5 lbs. litharge, PbO; 5 lbs. bicarbonate of sodium, HNaCO<sub>3</sub>; and 3¼ ozs. wheat flour, and pass them through a 40-mesh sieve, on the cloth. Spread the mixture out evenly, then, by lifting a corner of the cloth and drawing it forward, roll the mixture on itself, then take another corner in

the same way ; occasionally spread out the mixture and proceed as before until it is thoroughly mixed. Place the mixture in a box for future use.

## CHAPTER II.

### ASSAY OF ORES.

#### 3. To Prepare the Sample of Ore.

Take several pounds of rich silicious (q artz) ore, free from sulphur, arsenic, antimony, etc, break the large pieces by a hammer, then in an iron mortar (Fig. 4), so



FIG. 4.

that the largest pieces are not over about an inch through the longest diameter, then pass the ore through the crusher (Fig. 5), then shovel the ore on the tin sampler (Fig. 6),

where half is caught and half passes through,




FIG. 5.




FIG. 6.

repeating until the sample is reduced to about a pound. Now pass it through the

crushing rolls, and pulverize it on a bucking-board (Fig. 7) until it passes an 80-mesh sieve (some use a 100-mesh).




FIG. 7.

In conducting the operation on the bucking-board, place your left hand on the muller and grasp the handle with the right hand; throw your weight on the muller and move it back and forth, raising the handle when drawing toward you, and depressing it when pushing backward.\*

---

\*Ores can be pulverized in the iron mortar alone, or by other apparatus than is mentioned here.

Everything used in these operations must be perfectly clean. Particles of rich ore left from the last sample in the iron mortar, in the crusher, on the bucking-board, in the



After passing the ore through an 80-mesh sieve, mix it thoroughly on a rubber or an oil cloth. Spread the ore out evenly on the cloth, lift a corner of the cloth and draw it forward, rolling the ore on itself (merely sliding the ore on the cloth does not mix it), and proceed as directed for mixing flux (under 2), and put the sample into an ore-




FIG. 8.

pan (Fig. 8). Read the notes on ore-sampling and ore samples on page 29.

#### 4. Assay Ton Weights.

The ore is weighed by Avoirdupois, and the gold and silver by Troy weight. The

---

sieve, in the cleaning-brush, or on the mixing-cloth, carelessness or uncleanness in any of the operations or about the laboratory, make the results unreliable; and unless a person is strictly honest and is determined to do accurate work, he should not engage in this line of work.

After pulverizing rich ore, clean the apparatus with barren quartz or glass.



system of assay ton weights is very convenient and easily understood.

1 lb. Avoirdupois = 7000 Troy grains.

2000 lbs. = 1 ton.

$2000 \times 7000 = 14,000,000$  Troy grains in 1 ton Avoirdupois.

480 Troy grains = 1 oz. Troy.

$14,000,000 \div 480 = 29,166+$  Troy ozs. in 2000 lbs. Avoirdupois.

By taking as many milligrams of ore as a ton contains ounces, every milligram of gold or silver extracted is equivalent to an ounce to the ton. In one assay ton (A. T.) there are  $29,166+$  milligrams. Hence by taking one assay ton of ore, 1 milligram of gold or silver extracted = 1 oz. Troy to the ton of ore.  $2000 \text{ lbs.} : 1 \text{ A. T.} :: 1 \text{ oz. Troy} : 1 \text{ milligram.}$  Weighing by grains, the assay ton contains  $29,166+$  grains, hence 1 grain of gold or silver extracted = 1 oz. Troy to the ton of ore.

### 5. To Make the Assay.

Weigh an assay ton of the sample, prepared as directed under 3, on one of the pulp-balances\* (Figs. 9 and 10), taking a little




FIG. 9.

with the pulp-spoon (Fig. 11) from all parts of the sample.† Take about 85 grams, or 64 c.c., of the flux (Chap. I, 2), and mix the ore and flux in the same manner as directed for

---

\* Put the assay ton weight on the left-hand pan.

† A better method is to spread out the mixed ore in a thin layer, then take the sample, with a steel spatula having a square end, from all parts of the layer, driving the spatula to the bottom of the layer each time. This should be done gently, taking care not to jar the ore.

mixing sample (under 3), then pour it into a 20-grm. clay crucible (Fig. 12), in which




FIG. 10.




FIG. 11.




FIG. 12.

about 10 milligrams of C. P. silver has previously been placed. Weigh out another assay ton of the ore and proceed as before, omitting

the silver.\* Cover the charge in each crucible with about 15 grams of unfused powdered borax. Consider the charge in the crucible containing the silver No. 1, and the other No. 2. Place No. 1 on the left in the cru-




FIG. 13.

cible-furnace † (Fig. 13), and No. 2 on the right. You will know them by these positions through all the operations.

---

\* When assaying for gold only, add silver to both charges. When the approximate amount of gold in the ore is known, add an amount of silver to insure separation (see 8).

† If a gas-furnace is used, the crucibles may be put into the furnace before the fire is started. If a coke- or a coal-furnace is used, the fuel should be red hot and in such a condition, before the crucibles are put into the furnace, that the heat can be raised gradually. Make a nest in the glowing coals for the crucible, and pack the fuel around the crucible. Or put an old crucible into the fuel, and put the cru-

### 6. Fusion in the Crucible.

Fuse the charge, keeping the fire hot enough to keep the charge liquid. When the charge has subsided and is in a state of quiet fusion (the chemical reactions having all taken place, the charge may still have a con-



FIG. 14.

vection motion), urge the fire and after a few minutes remove the crucibles, one after another, from the fire, with the crucible-tongs (Fig. 14), give the crucible a circular, swinging movement, to wash the sides of the crucible, tap it on the floor or table to settle the

---

cible with the charge in its place, when the fire is in the proper condition. If, after the charge melts, the heat is checked sufficiently to stop the action, the assay is said to "freeze." In this case the assay is defective, and a new assay must be made.

Crucibles with the charges should be gently heated, before they are put into a hot fire, to prevent the crucibles from breaking, and to prevent "blowing" (see under sodium bicarbonate on page 48).



lead, and pour the liquid contents, at first slowly, then rapidly, into a mould (Fig. 15), which has previously been warmed.



FIG. 15.

When the assay has partly cooled, turn it out of the mould. The slag should be evenly colored, and should contain no globules of lead. Break the slag by a hammer (Fig. 16)




FIG. 16.

on an anvil (Fig. 17), hammer the lead button to a cube, flatten the corners, brush it (Fig. 18), and place it in its proper place on the button-tray (Fig. 19).






FIG. 17.



FIG. 18.






FIG. 19.




COMBINATION FURNACE.



COMBINED CRUCIBLE AND MUFFLE FURNACE.

FIG. 20.



## 7. Cupellation.

Place cupels (two more than the number of buttons) in the muffle of the muffle-furnace (Fig. 20), in the same relative positions that the crucibles occupied in the crucible-furnace. A little bone-ash should be sprinkled on the floor of the muffle.

When the cupels are at a red heat, and the muffle at a bright orange-red,\* charge in the buttons by the cupel-tongs (Fig. 21), and close the muffle until the black crust has disappeared from the melted buttons, then open the muffle. The lead oxidizes, and, together with the oxides of other metals, is

---

\* An idea of the approximate temperature in the muffle can be gained by Pouillet's scale of temperatures :

|                            | Deg. C. | Deg. F. |
|----------------------------|---------|---------|
| Incipient redness. . . . . | 525     | 977     |
| Dull red. . . . .          | 700     | 1,292   |
| Cherry-red. . . . .        | 900     | 1,652   |
| Deep orange. . . . .       | 1,100   | 2,012   |
| White. . . . .             | 1,300   | 2,372   |
| Dazzling white. . . . .    | 1,500   | 2,732   |


---

Foot-note continued on page 18.


absorbed by the cupel. When nearly all the lead has been oxidized, moving rainbow-

---


The direction of the fumes serves as a rough indicator of the temperature:



Too cold.



Too hot.



Right.



colored rings appear on the button, after which the button becomes duller, and the



FIG. 21.

cupellation is finished. If the button is less than one-third gold, it should be cooled slowly by bringing it to the front part of the muffle until the button begins to solidify, then moving it back to the hotter part of the muffle for a while, or by placing a red hot cupel over it, as it absorbs oxygen when molten and gives it out suddenly on solidifying, from which loss may result from "spitting."




FIG. 22.

Remove the cupels from the muffle, placing them on a tray (Fig. 22) in their proper

positions. When the buttons have partially cooled, remove No. 2 from the cupel by means




FIG. 23.




FIG. 24.




FIG. 25.

of a pair of pliers (Fig. 23), squeeze it to loosen the adhering bone-ash, and brush it

with the assay-button brush (Fig. 24), place it on the left-hand pan of the button-balance (Fig. 25), and weigh it.

### 8. Parting.

After noting the weight of the button, fuse it with sufficient silver to make the silver about  $2\frac{1}{2}$  times that of the gold,\* lay it on an anvil and flatten it by a few blows of a hammer. Pour nitric acid, 1.16 sp. gr. ( $21^{\circ}$  Baumé) into a test-tube (Fig. 26) to the depth of a little over the diameter of the test-tube, warm the acid, and then put the bead into it, and boil it until the acid becomes colorless. After all fine particles have settled, pour off the acid and boil again with the same amount of acid of 1.26 sp. gr. ( $32^{\circ}$  Baumé). Pour off the acid, fill up the test-tube with distilled water, and after the gold has settled, pour off the water, fill the

---

\* This is called "inquartation."



test-tube again with water, invert an annealing-cup (Fig. 27) over the mouth of the test-tube, and, by a quick movement, invert the test-tube, keeping the cup over the mouth of the test-tube, and fill the cup with water. The gold settles into the cup. Raise the



FIG. 26.



FIG. 27.

test-tube a little at a time until it is nearly even with the top of the annealing-cup (this should be done over a sink), then (after the gold has settled) quickly remove the test-tube, and after the water has run out, hold it to the top of the cup (using it as a pouring-rod) and pour the water out of the cup. With the last drop, by tapping the cup, bring all the gold together in the bottom of the

cup. Heat the cup to redness, and put it on the tray (Fig. 28) in its proper place. Do the same with the button, No. 1, (except that this button may need no additional silver). When cool, weigh No. 2. The difference between the weight of the button and the weight of the gold is the weight of the




FIG. 28.

silver. Weigh the gold of No. 1, which should closely agree with the weight of No. 2.

Read the notes on Fusion in the Crucible and on Cupellation on pages 32 and 34, and repeat the assay until you can make duplicate assays (duplicates by adding the same amount of silver, and duplicates without adding silver) that agree. Then practise on low grade ores of similar character.

### 9. Scorification Assay.

From the sample of ore prepared for the crucible assay (under 3), take  $\frac{1}{5}$  assay ton (A. T.), weigh out  $1\frac{1}{2}$  A. T. of C. P. granulated lead, mix about half of the lead with the ore, put the mixture into a scorifier (Fig. 29), smooth it down, mix the remaining lead



FIG. 29.

on the cloth or paper on which the ore and lead were mixed, so as to take up any particles of ore that may have been left on the mixing-cloth, spread it over the mixture evenly, and put about 0.20 grams of borax glass on top. Add a little silver to this, and make a duplicate, omitting the silver.\*

The scorification assay is made in the muffle, which should have a temperature of  $1050^{\circ}$  to  $1100^{\circ}$  C. When the muffle has reached

---

\* When assaying for gold only, add silver to both charges.

the required temperature, charge in the scorifiers\* by the scorifier-tongs (Fig. 30), in the relative positions as directed for the crucibles under 5. Close the muffle until fusion takes place, then open it. A ring of slag soon



FIG. 30.

forms which is increased by the addition of the lead oxide which forms, and in about 30 or 40 minutes, it closes over the metals. When the slag has closed over the metals, place, by the cupel-tongs, about 0.2 gram of powdered charcoal, wrapped in tissue-paper, on the surface of the slag, and close the muffle. This reduces some of the lead oxide, and the globules of lead fall through the slag and carry the gold and silver down, which had remained in the slag. When the

---

\* Scorifiers should be dry, and should be warmed with the charge by placing them on the furnace for some time before charging them into the muffle, to prevent them from breaking.

fusion becomes quiet, pour it into a mould. The lead buttons are treated in the same manner as already explained under the crucible assay.

Read the notes on the Scorification Assay on page 43, and repeat the assay until you can make duplicate assays (duplicates by adding the same amount of silver, and duplicates without adding silver) that agree.

#### 10. Lead Flux.

A mixture of

|   |    |       |
|---|----|-------|
| Bicarbonate of sodium, $\text{NaHCO}_3$ . . . . .         | 16 | parts |
| Carbonate of potassium, $\text{K}_2\text{CO}_3$ . . . . . | 16 | “     |
| Borax glass . . . . .                                     | 8  | “     |
| Wheat flour . . . . .                                     | 4  | “     |

#### 11. Fire Assay for Lead.

Prepare a sample of galena (lead sulphide) ore as directed under 3. Weigh out 5 grams of the ore, and mix it with 18 to 20 grams of lead flux, pour it into a

5-gram clay crucible (Fig. 31), cover it with dry fine common salt \* to the depth of about  $\frac{1}{4}$  inch, and stick 3 8-penny nails into the charge. Make a duplicate assay.

Make this assay in the muffle, which should be at a cherry-red heat before the crucibles † are charged in. After the crucibles are introduced into the muffle, close the muffle



FIG. 31.



FIG. 31a.

and, in about 20 minutes, raise the heat. In 30 to 40 minutes the assay will be in a state of quiet fusion; then take out the crucible and remove the nails ‡ with a pair of small tongs

---

\* Mix the salt on the cloth on which the ore and flux were mixed, so as to take up any particles of ore that may have remained on the cloth.

† See last paragraph of footnote on page 13.

‡ Another method is to seize the nails, above the slag, with a pair of straight tongs, and throw the lead off the nails by tapping the tongs on the top of the crucible. The same method should be used when nails are used in the assay for gold and silver (see page 65).



(Fig. 31*a*); after washing them in the slag, and tapping them on the inside of the crucible to remove adhering particles of lead, tap the crucible on the floor, and pour the assay into a mould. After cooling, hammer the slag off, flatten out the lead button and weigh it.

*Example.*—If the lead button weighs 3 grms.,  $3.00 \div 5$  (the amount of ore taken) = 60 per cent of lead; 60 per cent of 2000 lbs. = 1200 lbs. lead in a ton of ore. When lead is worth 4 cents a pound, 1200 lbs. are worth  $1200 \times \$.04 = \$48.00$ .



## CHAPTER III.

### NOTES ON THE ASSAY OF ORES.

#### 12. Notes on Ore-sampling and Ore Samples.

1. Large samples of ore should be crushed to a size not much larger than  $\frac{1}{4}$  inch, mixed on a cloth, spread out evenly, and divided into quarters. Remove two opposite quarters, mix the other two thoroughly, spread out, and quarter as before. Repeat this until the sample is reduced to the required size. After the sample is reduced to 2 or 3 lbs., it should be crushed finer before reducing it to a smaller sample.

Sampling can also be done by *channelling*, which consists in spreading the mixed ore out in a square, taking out samples in parallel grooves across the square, as far apart as the

width of the channels, then at right angles to these channels; or by a sampling tin, quartering-shovel, split shovel, or mechanical sampler.

2. Before pulverizing, damp samples must be dried on a water-bath (Fig. 32), or in a drying oven (Fig. 33) at a temperature not above  $100^{\circ}$  C.




FIG. 32.




FIG. 33.

3. After the sample is thoroughly mixed, pour it into an ore-pan. Mark the number of the sample, the character of the ore, and other data on a piece of paper or cardboard and put it into the pan with the ore.

4. Do not shake, tap, or otherwise disturb

the sample before weighing out the amount of ore for assay. If the ore is not immediately weighed out, the sample must be mixed again before weighing out the ore for assay. By standing, the heavy particles have a tendency to settle to the bottom of the pan on account of their weight, aided by the vibrations of the building, produced by various causes.

5. All the ore should pass the sieve. If scales of gold are left on the sieve, put them on the bucking-board, cover them with part of the fine ore and grind hard. Repeat until they pass the sieve. If the scales cannot be pulverized, weigh the sample that passes the sieve, and the scales separately, cupel the scales with a little lead-foil, and calculate the value per ton of ore, to which add the value of the assay of the ore that passed the sieve.

For methods of assaying ores and materials containing scales of gold, or other coarse

metal, and for a method for calculating the value of such ores, see Chapter VIII.

### 13. Notes on Fusion in the Crucible.

1. The ore and flux must be intimately mixed, so that as the lead is reduced it can come in contact with the gold freed by the pulverization, and by the fusion of the ore.

2. The object of the fusion is to collect the gold and silver in a button of lead, reduced from the litharge, and to form a fusible slag with the fluxes and gangue of the ore.

3. Crucibles should not be over three-fourths full, and less in case of sulphide ores.

4. The assay swells when heated; prevent it from boiling over.

5. Causes of boiling over: (*a*), too much borax, especially in oxidized ore; (*b*), too much soda; (*c*), unfused borax mixed with the charge; (*d*), rapidly heating a charge containing nitre.

6. Boiling over can be prevented by re-

moving the cover, if covered, checking the heat, or by throwing a teaspoonful of salt into the crucible.

7. If the slag is pasty, add borax. If accuracy is required, make another assay, fluxed as indicated by the first assay. The fluxing of other than silicious ores will be explained when they are taken up.

8. After pouring, examine the crucible. If the crucible contains shots of lead or pasty masses, the assay is defective.

9. The fusion can be made in a muffle; the temperature should be about the same as in the scorification assay. When the fusion is made in the muffle,  $\frac{1}{2}$  an assay ton of ore is usually taken, and fluxes in the same proportion.

For convenience and economy, where many assays are made, use a soft-coal furnace containing two large muffles, one above the other. The fusion can be made in the lower

muffle while cupellation is going on in the upper muffle.

#### 14. Notes on Cupellation.

1. The cupel should be about one-half heavier than the button.

2. Spiriting of the lead button sometimes happens when there is too strong a draught, or when the button contains volatile elements as arsenic, antimony, sulphur, carbon, bismuth, or mercury. Examine the cupel for small beads of metal.

3. When the muffle is not hot enough, put a piece of charcoal in the front of the muffle, which will raise the temperature. Some also use this to equalize the temperature in the muffle, as the front of the muffle has always a lower temperature. The temperature increases from the front to the back of the muffle.

4. After the cupellation is finished, the button should be left in the muffle a few



minutes to remove all remaining traces of lead.

5. When the button begins to solidify, it “flashes,” suddenly “brightens,” which is due to the sudden disengagement of the latent heat of fusion.

6. Buttons containing a large proportion of silver will “spit,” if cooled rapidly. This “spitting,” “sprouting,” or “vegetation,” as it is called, may be prevented in three ways: (*a*), by drawing the cupel to the front of the muffle to partly cool the cupel, and when the button begins to solidify, pushing it back to the hotter part of the muffle where the outside of the button melts, and the solidification goes on from below; (*b*), by inverting a red hot cupel over the cupel and button; (*c*), by closing the muffle, withdrawing the fire, and allowing slow cooling to go on. The “spitting” is due to the absorbing of oxygen by the silver when molten, and giving it out suddenly when solidifying.

7. Silver is volatile at a high temperature, also gold, to some extent. Silver begins to volatilize at a white heat.

A strong draught of air cools the cupel, and prevents the oxides from being absorbed as fast as formed.

The longer the time required for cupellation, the more the loss by volatilization and absorption by the cupel.

Some assayers keep the muffle at a low enough temperature to form a ring of litharge crystals ("feathers") around the cupel. This is liable to give too high results, as the lead may not be completely removed from the button. When cupelling with "feathers," move button to hotter part of muffle to blick.

8. Sometimes during cupellation the action stops, and the button solidifies. This is called "freezing," and is due to the oxides forming more rapidly than they can be absorbed, or to the low temperature of the

muffle. If the former, an addition of lead will remedy it. If the latter, raise the temperature. The results are not reliable.

### 15. Notes on Parting.

1. When the bead contains from two to three times as much silver as gold by weight, nitric acid will dissolve the silver. This separation is called "parting." Not all the silver will dissolve, but it is sufficiently accurate for ordinary work.

2. If the bead is perfectly white, it usually needs no additional silver to "part" it. If it is yellow, it needs an addition of from  $1\frac{1}{2}$  to  $2\frac{1}{2}$  times its weight of silver (according to the degree of yellowness), to part it. The button and the silver may be fused by the blowpipe on charcoal, or by wrapping them in lead-foil and cupelling. Before parting the button, it is flattened by a hammer, and if large, passed through the rolls (Fig. 34),

after which it is annealed by heating it to redness.




FIG. 34.

Silver fuses at  $954^{\circ}$  C., and gold at  $1045^{\circ}$  C.  
The silver melts first and the gold sinks in it.

When the fusion is made by the blowpipe, care must be taken to continue the heat until the gold is fused.

3. Parting can be effected in a test-tube, in a small porcelain crucible, or, if the button is large, in a parting-flask (Fig. 35). If the separation is made in a porcelain crucible, the



FIG. 35.

gold is also dried and annealed in the same crucible. In annealing, the crucible should be heated to redness. The heat must be raised gradually to prevent the gold from being scattered by the steam formed.

When the separation is made in a porcelain crucible, after pouring off the wash-water, bring the gold together, and turn the crucible so as to collect the remaining water on the



opposite side from the gold. The water can then be removed by filter-paper.

A needle, stuck into a soft piece of wood for a handle, is convenient to loosen the gold from the cup, after annealing. The gold can be weighed in this form, or some wrap it in lead-foil and cupel it.

4. Use dilute acid, 1.16 sp. gr. (21° Baumé), for the first boiling, and fresh acid of 1.26 sp. gr. (32° Baumé) for the second boiling. If the acid is warmed before the bead is put into it, the gold does not break up into such fine particles. By boiling a second time, the silver is more completely removed, the gold becomes more compact, and there is less danger of loss. By boiling the acid after it is concentrated to about 1.42 sp. gr., it dissolves gold in appreciable quantities.

To prevent violent action and so keep the gold from breaking up into fine particles, after heating the dilute acid to nearly boiling, drop the bead into it and continue to heat it



on a sand-bath or hot plate for ten or fifteen minutes; pour off the acid, add stronger acid, boil and proceed as directed above.

5. If the gold, after parting, weighs more than one-third of the weight of the bead, the gold contains silver and must be fused again




FIG. 36.

with from 2 to 3 times its weight of silver, and again parted.

6. If from  $2\frac{1}{4}$  to  $2\frac{1}{2}$  times as much silver as gold is present, the gold remains in one piece after parting; if much more silver is present, the gold breaks up into small particles, some of which may float on the surface of the acid.

By touching them with a glass rod, or by dropping water on them, they can be made to sink. Set the test-tube in the rack (Fig. 36) until all the gold has settled, and bring the particles together by tapping the bottom of




FIG. 36a.

the test-tube with the fingers, before pouring off the acid.

7. If, in beginning to boil, the bead turns black and the action stops, it must be fused with additional silver.

8. Small glass tubing in the acid while boiling will prevent "bumping."

**16. Notes on the Scorification Assay.**

1. This method is especially applicable to rich gold and silver ores. The scorification assay gives higher (uncorrected) results for silver.

2. If the slag is pasty, add borax. The slag may be rich.

3. Borax makes the slag fluid, but if too much borax is used, the slag will cover the bath of metal too soon.

4. If the muffle is not hot enough, when the scorifiers are charged in, gold may remain in the slag.

5. Pasty slag or slag from rich ores should be ground up, fluxed with a little borax and argol, and scorified as the ore. Use the same scorifier in which the first scorification was made, and cupel the button with the first one obtained.

6. If the ore is low grade, make a number of assays, place the buttons together in a

scorifier, add a little borax glass, and scorify them to the proper size for cupellation. In this case the slag need not cover the bath of metal.

7. The treatment of other than silicious ores, and ores containing other elements, will be explained when they are taken up.

#### 17. Notes on the Fire Assay for Lead.

1. The fire assay for lead gives only approximate results. If the ore contains gold, silver, iron, copper, or other metals, some or all may be reduced with the lead. If the button is brittle, it contains antimony, sulphur, etc.; if hard, copper, iron, etc. Arsenic carries lead into the slag, and forms with the iron a separate, hard, and brittle button. Some lead may volatilize, and some oxidize and go into the slag. The button can be cupelled for the precious metals and the weight deducted.

2. If the assay is made in a crucible-furnace, the crucible should be covered.

Avoid too high a temperature. Lead and lead sulphide are volatile at a high temperature. The heat should not be above redness, at least for the first 20 minutes.

3. Oxidized and carbonate ores need no nails.

4. The assay can be poured, or allowed to cool in the crucible, after which the crucible is broken and the lead extracted.

5. The slag can be assayed, and the lead recovered, added to the first button.

6. Lead fluxes :

Mix and take from 18 to 20 grams for 5 grams of ore, and to ores containing sulphur, add 3 8-penny iron nails, or use a wrought-iron crucible. With ores containing phosphorus, use additional borax glass to prevent pasty slag.



|    |                          |       |       |       |            |
|----|--------------------------|-------|-------|-------|------------|
|    |                          | (1)   | or    | (2)   |            |
| 1. | Sodium bicarbonate.....  | 16    |       | 100   | parts      |
|    | Potassium carbonate..... | 12    |       | 50    | “          |
|    | Wheat flour..            | 12    |       | 15    | “          |
|    | Borax glass.....         | 4     |       | 25    | “          |
|    | Salt.....                | cover |       | cover |            |
| 2. | (Plattner.)              |       | (1)   | or    | (2) or (3) |
|    | Potassium carbonate..... | 5     | 6½    |       | 2 parts    |
|    | Sodium bicarbonate.....  | 6½    | 5     |       | 2 “        |
|    | Flour.....               | 2½    | 1     |       | 1 “        |
|    | Borax glass .....        | 2½    | 2½    |       | 1 “        |
|    | Salt .....               | cover | cover |       | cover      |
| 3. | Ore .....                |       |       | 10    | grams      |
|    | Potassium cyanide.....   |       |       | 35    | “          |
|    | Salt.....                |       |       | cover |            |
|    | No nails.                |       |       |       |            |




Potassium cyanide is a strong reducing agent, but, if used with ores containing iron, copper, and other metals, it reduces them also with the lead.



## CHAPTER IV.

### FLUXES AND REAGENTS.

*Sodium Bicarbonate*,  $\text{NaHCO}_3$ , or its corresponding potassium salt,  $\text{KHCO}_3$ , acts as a basic flux, a desulphurizing agent, and in some cases, as an oxidizing agent. Heat reduces it to sodium carbonate, which on being fused with silica, forms fusible silicates, and liberates carbon dioxide. The carbon dioxide liberated oxidizes sulphur, and metallic iron, zinc, and other metals, which then go into the slag. With sulphide ores, under certain conditions, it forms sodium sulphate and sodium sulphide.




---

\* The atomic weights from the sixth annual report of the committee on atomic weights are used in this book (see p. 136).

A charge containing sodium bicarbonate should be heated gently at first, or the carbon dioxide and steam, which are given off at a comparatively low temperature, may blow out some of the fine ore. The carbonate fuses at about 800° C., and absorbs such infusible substances as lime, alumina, etc.

When equal molecules of silica and sodium carbonate are fused together, sodium bisilicate is formed, and carbon dioxide liberated.



When fusion takes place, the silica displaces the CO<sub>2</sub> in the sodium carbonate. The escape of the CO<sub>2</sub> causes a brisk effervescence to take place.

According to the above equations, it takes over 2.78 times as much sodium bicarbonate as silica to form sodium bisilicate.

Sodium carbonate forms a double salt


with potassium carbonate, which fuses at a lower temperature than either alone.

When silica, sodium carbonate, carbon, borax, and other substances are fused together, as in an assay, of course many other reactions take place.

*Litharge*, PbO, is used in the crucible assay of gold and silver ores. It is a basic flux, dissolves metallic oxides, oxidizes sulphur and other oxidizable substances, and supplies the lead in the crucible assay.

Nearly all litharge contains silver, the amount of which must be determined, when used in the assay for silver. It can be freed from red lead, Pb<sub>3</sub>O<sub>4</sub>, by fusing in a crucible, pouring, and keeping it from the air while cooling. It is claimed that red lead oxidizes silver and thus causes loss.

With silica it forms a lead silicate.



It takes over 3.69 parts of lead oxide to

one part of silica by weight to form lead silicate, which is easily fusible, and more fluid, when fused, than sodium silicate. It forms fusible double silicates, but has no action on lime or magnesia except in the presence of silicates and borates.

Metallic oxides that are infusible or almost infusible alone are easily dissolved by lead oxide, with which they form a basic slag, which attacks the crucible by uniting with the silica in the crucible.

*Borax*,  $\text{Na}_2\text{B}_4\text{O}_7$ .—The unfused or crystallized borax,  $\text{Na}_2\text{B}_4\text{O}_7, 10\text{H}_2\text{O}$ , contains over 47 per cent water. When mixed with the charge of ore and flux, the fused borax (borax glass) should be used, as the unfused borax is apt to cause loss by swelling and thus forcing part of the charge out of the crucible. It is an acid flux, and will flux sulphides, arsenides, metallic oxides, lime, etc. It also forms fusible compounds with silica.

*Silica*,  $\text{SiO}_2$ , is an acid flux. It forms compounds with all the bases, and is used in the assay of ores containing lime, magnesia, baryta, iron, etc. Pulverized silica (pure white quartz) should be used.

As a substitute, ground glass can be used. Window-glass is probably the best, which is a silicate of sodium and calcium. Bohemian glass is a silicate of potassium and calcium, and is not easily fusible. Bottle-glass is a silicate of sodium, aluminum, calcium, iron, etc. Flint glass contains lead, and hence cannot be used in the assay for lead. Enamelled glass should not be used, as it contains arsenic, antimony, tin, etc.

*Flour*.—Wheat flour is a strong reducing agent. One part of flour will reduce about 15 parts of lead from lead oxide.

*Argol* is a reducing agent, and basic flux. It contains other carbonaceous matters than the pure potassium bitartrate,  $\text{KHC}_4\text{H}_4\text{O}_6$ , and therefore has a greater reducing power. Heat

changes it to potassium carbonate and carbon. Its reducing power can be determined by fusing it with litharge and sodium bicarbonate. One part of argol will reduce from 5 to  $8\frac{1}{2}$  parts of lead.

*Potassium Cyanide*, KCN, is a strong reducing and desulphurizing agent. It combines with oxygen, forming cyanate,



and with sulphur, forming thiocyanate,



Potassium cyanide is extremely poisonous.

*Charcoal*.—Powdered wood-charcoal is used. It is a reducing agent. It absorbs water and gases, and has about 3 per cent ash,  $2\frac{1}{2}$  per cent hydrogen,  $1\frac{1}{2}$  per cent oxygen, and 93 per cent carbon. At low temperatures it forms carbon dioxide; and at high temperatures, carbon monoxide, when heated with metallic oxides, from which it takes the oxygen. As its reducing power varies under



different conditions, its reducing power should be determined under the conditions under which it is to be used. Ordinarily 1 part of charcoal reduces from 20 to 30 parts of lead.

*Iron* in the form of nails and wire is used in the assay of sulphide ores. It forms iron sulphide with the sulphur, which is dissolved by the slag, if only a moderate quantity is present. A large quantity will form a separate layer of matte.

*Potassium Nitrate*,  $\text{KNO}_3$  (nitre, or saltpetre), oxidizes most oxidizable substances. It melts at  $339^\circ$  (Person),  $352^\circ$  (Carnelly); and, at a higher temperature, it is decomposed, yielding a large volume of oxygen. The oxygen combines with the sulphur of sulphide ores, and also oxidizes most of the metals except gold and some of the platinum group. One part of nitre oxidizes about 4 parts of lead.

*Salt*, sodium chloride,  $\text{NaCl}$ , is used as a

cover. In an open crucible, it melts and volatilizes at a red heat, and forms a liquid cover, which excludes the air and prevents loss by ebullition. It washes the sides of the crucible, and forms fusible compounds with silica, antimony, and arsenic.

*Metallic Lead*, in the form of sheet lead, is used in cupelling beads and in the bullion assay. Granulated lead (test-lead) is used in the scorification assay. As nearly all lead contains silver, its silver contents should be determined, and the proper correction made, when used in the assay for silver.

Lead acts as a basic flux, and a solvent or collector for gold and silver.

## CHAPTER V.

### S L A G S .



One of the aims in making up an assay charge is to flux the ore so as to produce, when fused, a liquid slag. If the slag under this condition is not liquid, it may retain some of the precious metals. If the charge is of such a character that it fuses, and becomes liquid at a low temperature, its reducing power is diminished; and, if the slag becomes very liquid in the beginning of the fusion, the reduced lead particles may drop to the bottom of the crucible before they come in contact with all the gold in the charge.

Slags are usually made silicates, which are made up of a basic oxide, as sodium oxide, lead oxide, lime, or baryta, combined with silica, which is acid in character.

Silicates are classified as subsilicates, monosilicates, bisilicates, etc., according to the ratio of the oxygen in the base to the oxygen in the silica.

| Name.                | Sodium Silicate.                     | Oxygen Ratio. |
|----------------------|--------------------------------------|---------------|
| Subsilicate .....    | $4\text{Na}_2\text{O}.\text{SiO}_2$  | 2 : 1         |
| Monosilicate ....    | $2\text{Na}_2\text{O}.\text{SiO}_2$  | 1 : 1         |
| Bisilicate.....      | $\text{Na}_2\text{O}.\text{SiO}_2$   | 1 : 2         |
| Trisilicate. ....    | $2\text{Na}_2\text{O}.3\text{SiO}_2$ | 1 : 3         |
| Sesquisilicate ..... | $4\text{Na}_2\text{O}.3\text{SiO}_2$ | 2 : 3         |

The fusibility of a slag depends on the character of the bases, and on the percentage of silica it contains. The silicates of lime and alumina are the least fusible. Slags of the composition  $\text{CaO}.\text{SiO}_2$  and  $4\text{CaO}.3\text{SiO}_2$  are fusible, and those of a higher percentage of lime are almost or entirely infusible at the temperature of the assay-furnace.



It takes over 1.6568 times as much limestone,  $\text{CaCO}_3$ , as silica,  $\text{SiO}_2$ , to produce a slag of the composition  $\text{CaO.SiO}_2$ ; or, to one assay ton, 29.1666 grams, of limestone, it takes 17.6041 grams of silica.

Neither lime nor silica can be fused at the temperature of the assay-furnace; but, if they are pulverized and intimately mixed in the proportions given above, they unite, at the temperature attained in the furnace, forming a fusible compound (calcium silicate) called a *slag*. To this must be added litharge to supply the lead in which to collect the gold and silver. Sufficient flour or argol is added to reduce a lead button weighing about 20 grams. Soda, litharge, and silica are added in such proportions as to make a liquid slag (when hot), which dilutes the calcium silicate, thus making it more fluid, in order that the reduced metallic particles of lead, gold, and silver can sink to the bottom of the crucible on account of their greater specific gravities.

A charge for a gangue of limestone would be about as follows:



|                        |           |
|------------------------|-----------|
| Limestone.....         | 1 A. T.   |
| Silica.....            | 1½ A. T.  |
| Sodium bicarbonate.... | 42 Grams. |
| Litharge.....          | 42 “      |
| Flour.....             | 1.7 “     |
| Borax-glass.....       | 10 “      |
| Salt.....              | Cover.    |

The borax fluxes the lime and other oxides, and helps to make the slag liquid. Borax becomes very liquid, when fused, so if not all the borax added is needed for a flux, it will make the slag more liquid by simply diluting it. The exact proportions to make a certain slag with each ore cannot be calculated, unless a chemical analysis is made of each ore. In assaying, this is out of the question, so the assayer is careful not to add an excess of a flux that is infusible in itself, but he adds an excess of a flux that is very



fusible, which, by merely diluting the slag, makes it more liquid.

With magnesia,  $4\text{MgO}.3\text{SiO}_2$  and  $2\text{MgO}.3\text{SiO}_2$  make fusible slags.



It takes over 1.86 times as much magnesium carbonate as silica to form the slag,  $4\text{MgO}.3\text{SiO}_2$ ; or, to one assay ton, 29.166 grams, of magnesium carbonate it takes 15.68 grams of silica.

With baryta,  $\text{BaO}.3\text{SiO}_2$  and  $\text{BaO}.4\text{SiO}_2$  make fusible slags.

Silicates of alumina are not fusible alone at the temperature of the assay-furnace. If a base is added, as lime, lead oxide, iron oxide, etc., making them double silicates, they become fusible. A fusible slag can be made by adding sufficient lime and silica to make the

oxygen in the lime between one and two times that in the alumina, and the oxygen in the silica between one-half and twice the sum of the oxygen in the lime and the alumina. Clays are of various compositions, as  $2\text{Al}_2\text{O}_3.3\text{SiO}_2$ ,  $\text{Al}_2\text{O}_3.2\text{SiO}_2.2\text{H}_2\text{O}$ , etc.

The most fusible silicates are those of lead, potassium, and sodium, after which come iron and copper. An excess of silica is an advantage in the fusibility of slags in which the base is lime or magnesia, but a disadvantage in those in which the base is sodium, lead, etc. The subsilicates, or basic silicates, are the most fusible; and the fusibility of a slag decreases as the proportion of silica increases, except in lime and other silicates, already noted. Double silicates (silicates having two bases) are usually more fusible than those that have only one base.

## CHAPTER VI.

### THE ASSAY OF SO-CALLED REFRACTORY ORES.

The assaying of silicious gold and silver ores has been discussed in the previous chapters. When an ore is oxidized, or contains sulphur, antimony, arsenic, tellurium, etc., it needs a different treatment.

Such ores should be fluxed with a view to keep sulphur, arsenic, etc., out of the lead button; and, if one assay ton of ore is taken, to reduce a lead button of from 20 to 30 grams. If the button weighs less than 20 grams, there is danger of leaving some gold in the slag, especially in rich ores. Large buttons give low results for silver, as silver is lost by being absorbed by the cupel, and by volatilization in proportion to the amount of lead present.

The crucible assay is preferred for low grade ores, as a larger amount of ore can be taken. For rich ores, especially for rich silver ores, the scorification assay has advantages.

Ores containing sulphur, antimony, arsenic, etc., have a reducing effect; those containing the higher oxides of iron, copper, manganese, etc., have an oxidizing effect. The former may reduce too large a button; the latter too small a button, or none at all. The reducing action can be corrected by an addition of nitre, and the oxidizing action by an addition of flour, argol, or charcoal. Some ores contain a mixture of oxidizing and reducing agents.

By making a preliminary assay, the proper amount of oxidizing or reducing agents to be added may be calculated. After some experience, the student will know, from the appearance of the ore, about how much of the one or the other reagent to add.

*Preliminary Assay.*—If the ore contains sulphur, antimony, arsenic, or other reducing elements, take 5 grams of ore, 50 grams of litharge, 18 grams sodium bicarbonate, 5 grams silica, borax cover. Put the charge into a 10-gram clay crucible, and proceed as directed under 6. Detach the lead button and weigh it. Let us assume, for convenience of calculation :

|   |  |
|---|--|
| 1 assay ton . . . . .                                       | 30 grams   |
| 1 part of nitre oxidizes . . . . .                          | 4 parts of lead (3½ to 4)                            |
| Lead button reduced by 5                                    |  |
| grams of ore . . . . .                                      | 7 grams  |
| 1 assay ton would reduce . . . . .                          | 42 grams of lead                                     |
| This is in excess of the weight                             |  |
| desired, about . . . . .                                    | 20 grams   |
| 20 ÷ 4 (1 part of nitre oxidizes about 4 of lead) . . . . . | 5 grams of nitre to be added to one assay ton of ore |

Sometimes by using the amount of nitre calculated from a preliminary assay, very little or no lead is reduced. This may happen when an ore contains much iron oxide, and some sulphur. The litharge combines with the iron oxide, and some of the lead

unites with the sulphur. An addition of nitre or a large addition of litharge will remedy this.

Suppose the ore has an oxidizing power. Take 5 grams of ore, 30 grams litharge, 18 grams sodium bicarbonate, 4 grams silica, 1 gram flour (or 2 grams argol), borax cover. Proceed as directed above. One gram of flour should reduce from 12 to 16 grams of lead, if the ore is neutral. From the results obtained, the weight of the reducing agent that must be added to bring down a button of the proper weight can be calculated.

Let us assume, for convenience of calculation:

|   |                          |       |           |
|---|--------------------------|-------|-----------|
| 1 assay ton.....  | 30 grams                 |       |           |
| 1 gram flour reduces .....                                    | 14 grams lead (12 to 16) |       |           |
| 5 grams ore with 1 gram flour gave                            | 11                       | “     | “         |
| Hence, 5 grams ore oxidized                                   |                          |       |           |
| (14 — 11) .....   | 3                        | “     | “         |
| 1 assay ton (6 × 5 grams) will oxidize                        | 18                       | “     | “         |
| To neutralize the oxidizing effect, it will take (18 ÷ 14)... | 1.285                    | grams | flour     |
| To bring down a button (23.8 grams), it will take.....        | 1.7                      | grams | flour     |
| Or 1 assay ton of the ore requires                            | 3                        | “     | “ (2.985) |



The oxidizing and reducing powers of ores are different under different conditions. When the charge is acid, the sulphur oxidizes to  $\text{SO}_2$ ; and, when much soda is present, the sulphur oxidizes to  $\text{SO}_3$ , and sulphates are formed. Under the latter condition more lead would be reduced.

A preliminary assay cannot be made for each ore in an office where much assaying is done.

*Desulphurization by Means of Iron Nails.*  
—Ores containing only a small percentage of sulphur can be assayed by adding two, three, or more (according to the amount of sulphur in the ore) 20-penny iron nails, and sufficient silica to make a subsilicate with the bases present, to the charge as directed to be made under 5. If lime or magnesia are among the bases, add silica to make the slag given in Chapter V. The sulphur forms iron sulphide with the iron, a certain amount of which dissolves in the slag. If more is

formed than the slag can take up, a separate layer of matte is formed. If a matte forms, separate the lead button, grind up the matte and slag, mix with 1 assay ton litharge, 1 gram flour (or 2 grams argol), nails and silica as directed above, and use borax for a cover. Proceed as in a regular assay. In such an assay the slag would be very basic, without the addition of silica, and would attack the crucible by combining with the silica in the crucible.

Cupel this button with the first one obtained, or, if too large for cupellation, scorify the buttons to the proper size.

Or remove the matte from the slag, pulverize it, put it into a scorifier, and roast it "dead" (see under Roasting), then add the first button obtained, silica, test-lead, and borax-glass, and scorify as directed under 9.

If a button is obtained in any assay that is very large, it should be scorified to the proper size. There is less loss in scorification

than in cupellation ; but, when the lead in a button is small in proportion to the silver, there is more loss of silver in scorification than in cupellation.

If the button is of the right size, but hard from the presence of iron, copper, or other base metals, or brittle from the presence of sulphur, arsenic, antimony, etc., scorify it with from 10 to 25 grams of test-lead and a little borax-glass.

*Roasting.*—Ores containing a large percentage of sulphur should be roasted. If the ore contains iron pyrites, put 1 assay ton of the ore into a clay roasting-dish, and perform the roasting in a muffle. Keep the temperature low at first or the ore will fuse and agglomerate. The rapid disengagement of volatile elements would also cause loss mechanically. Raise the temperature gradually, and stir the ore with a stout wire or iron rod, made by flattening one end, and bending it at a right angle, about an inch from the end. When,

on stirring, no more burning is seen, gradually raise the temperature to a dull red heat. Then take the roasting-dish with the ore out of the muffle, and allow the ore to cool, or pour it on an iron plate to cool. When cold, if 1 assay ton was taken, mix it with 42 grams litharge, 42 grams sodium bicarbonate, from  $\frac{1}{2}$  to  $1\frac{1}{2}$  assay tons of silica, according to the percentage of iron present; from 2 to 4 grams flour, according to the amount of sesquioxide of iron formed; and use about 15 grams unfused powdered borax for a cover (or mix with from 8 to 10 grams borax-glass, and use salt for a cover).

If all the sulphur has been burned out ("dead" roasted), and the iron is oxidized to sesquioxide, it needs the reducing agent prescribed. If not all the sulphur is burned out, the ore may still have a reducing power; and the addition of a reducing agent may bring down too large a button.

When the percentage of sulphur is very

high, add an equal weight of silica to the ore before roasting, which will help to prevent the ore from agglomerating. Take the amount of silica added into consideration in fluxing the ore.

Ores can also be roasted over the furnace in a smooth, chalked, cast-iron pan, or in a crucible in the crucible-furnace. Proceed as directed above, and, if the roasting is done in a crucible, use the same crucible in which to make the fusion.

If sulphide ores are not roasted, oxysulphurets\* may form, which are very fusible, but resist reduction at the temperature of the assay-furnace, and carry silver into the slag. In the fusion of ores containing arsenic and antimony, arseniates and antimoniates are formed, which carry silver into the slag. These ores should be roasted. Mix them with silica before roasting; and, after roast-

---

\* Ricketts and Miller's Notes on Assaying, pp. 94 and 95; Hiorns's Practical Metallurgy and Assaying, page 258.



ing, add some powdered charcoal to reduce arseniates and antimoniates, which may have been formed. Burn out all the charcoal.

When sulphates are formed during roasting that cannot be broken up at a dull red heat, mix the cool, roasted ore with some ammonium carbonate, cover, and heat until fumes cease. This converts the sulphates into ammonium sulphates, which are volatilized. Treat copper sulphide ore in this way.

*Corrected Assays.*—Slags from rich ores, or from ores containing much ferric oxide,  $\text{Fe}_2\text{O}_3$ , or slags containing many metallic oxides, should be assayed, and the button added to the first button. The slag from ores containing zinc, arsenic, and antimony usually contain silver, if the ore contained silver. The cupels absorb silver and gold to some extent. Cupels in which large buttons of silver were cupelled should be assayed. Oxides of the base metals carry gold and silver into the



cupel. Copper oxide in particular carries much gold and silver into the cupel.

*Assay Charges for Slags and Cupels.*—  
*Slag:* If one assay ton of ore was taken, mix the pulverized slag with 1 assay ton litharge, 1 gram flour, silica, if basic, and use borax for a cover. A small amount of soda may be added. Charges should vary according to the character of the slag. Scorification slags generally need only a little flour or argol, and a little borax. *Cupels:* The phosphates present in the bone-ash make the slag from cupels pasty. Fluorspar or borax will make the slag fluid. For assaying a cupel in which a button of 20 grams or more has been cupelled, proceed as follows: Remove the saturated part of the cupel, pulverize it, mix it with 50 grams litharge, 30 grams sodium bicarbonate, and 30 grams borax-glass. The slag and the cupel from the same assay can be fused together, fluxed as follows: 50 grams litharge, 50 grams sodium bicarbonate, 1

gram flour or 2 grams argol, from 45 to 50 grams borax-glass; and an amount of silica according to the character of the slag.

*General Crucible Charges.*—From the foregoing discussion, the student will see that different ores require different fluxes. For silicious ores free from sulphur, etc., the following charge will answer:

|                         |                        |
|-------------------------|------------------------|
| Ore.....                | 1 A. T.                |
| Litharge .....          | 42 grams               |
| Sodium bicarbonate..... | 42 grams               |
| Flour .....             | 1.7 grams              |
| Cover.....              | 15 grams unfused borax |

For ores containing only a small amount of sulphur add to the above charge one, two, or more 20-penny iron nails, and silica in proportion to the bases present, as explained in Chapter V.

Roast ore containing much sulphur, arsenic, etc., add silica, and, if roasted “dead,” add also from  $\frac{1}{4}$  to 1 gram flour to the above formula, according to the amount of sesquioxide of iron present.

Ores with a gangue of lime or baryta need more soda, borax, and silica.

*Mitchell's Formula :*

|                              |   |       |
|------------------------------|---|-------|
| Ore . . . . .                | 1 | A. T. |
| Sodium bicarbonate . . . . . | 1 | " "   |
| Litharge . . . . .           | 5 | " "   |
| Borax-glass . . . . .        | 1 | " "   |
| Salt . . . . .               |   | Cover |

And argol or nitre to bring down a button of the required size.

*Aaron's General Formula :*

|                     |      |       |
|---------------------|------|-------|
| Ore . . . . .       | 1    | A. T. |
| Litharge . . . . .  | 1½   | " "   |
| Soda . . . . .      | 3    | " "   |
| Borax . . . . .     | ½    | " "   |
| Flour . . . . .     | 1/10 | " "   |
| Iron, 1 to 3 nails. |      |       |
| Salt . . . . .      |      | cover |

Melt and leave in strong fire about 20 minutes after fusion.

Some assayers reduce all the lead in the litharge used, and slag the gangue with borax,

soda, and silica. Aaron was the first to describe this method. Beginners usually do not succeed very well with this method.

*Special Methods.*—For the assay of ores and materials containing copper for gold and silver, see Chapter IX.

*Telluride Ores* may be treated in a beaker with aqua regia (three parts of hydrochloric acid to one part nitric acid,  $3\text{HCl} + \text{HNO}_3 = \text{NOCl} + 2\text{H}_2\text{O} + \text{Cl}_2$ ), which dissolves the gold and the tellurium. Add excess of hydrochloric acid, and heat until all the chlorine and hydrochloric acid are driven off. Filter, wash, and precipitate the gold and tellurium with a current of sulphur dioxide gas, which can be made by burning sulphur, or by treating copper with sulphuric acid,  $\text{Cu} + 2\text{H}_2\text{SO}_4 = \text{CuSO}_4 + 2\text{H}_2\text{O} + \text{SO}_2$ . Treat the precipitate with nitric acid, which dissolves the tellurium. Filter, dry the gold residue, wrap it in lead-foil with  $2\frac{1}{2}$  times its weight of silver, cupel, part, and weigh as usual. When

much silver is present, or other interfering elements, not all the gold may dissolve. Precipitate the gold and the tellurium in the beaker containing the residue, then dissolve the tellurium with nitric acid, filter, and wash the residue. Dry the gold and residue, and proceed as with a regular assay. If silver is also to be determined, precipitate the silver in the filtrate and proceed as directed above for copper ore. It is convenient to treat an assay ton of ore.

CRUCIBLE CHARGES. (Tabulated from Ricketts and Miller's Notes on Assaying).

| Ore.                        | A. T. Ore. | A. T. Litharge. | A. T. Sodium Bicarbonate. | Grams Argol. | Grams Nitre. | Grams Borax Glass. | Cover. | Remarks.  |
|-----------------------------|------------|-----------------|---------------------------|--------------|--------------|--------------------|--------|---|
| Quartz, rich.....           | 1          | 2               | 1                         | 1½           | .....        | 10                 | salt   | Same charges, with addition of from 1 to 3 A. T. of silica. If the gangue is magnesite or barite, increase both the soda and silica.  |
| Quartz, low grade.          | 2          | 3               | 1½                        | 1½           | .....        | 10                 | salt   |   |
| Quartz, tailings. . .       | 4          | 2               | 4                         | 2            | .....        | 10                 | salt   |   |
| Pure ore, basic gangue..... | .....      | .....           | .....                     | .....        | .....        | .....              | .....  |   |
| Galena .....                | 1          | 1               | 1                         | .....        | 20           | 10                 | salt   | Roast, and add silica, 2 A. T.<br>Mix 1 A. T. ore with 1 A. T. clean sand and roast; then add a large spoonful of ground charcoal and heat until no more sparks are seen.   |
| Arsenopyrite.....           | 2          | 3               | 1½                        | 2½           | ..           | 10                 | salt   |   |
| Antimony sulphide ..        | ..         | 2               | 1                         | 2            | ..           | 10                 | salt   |   |
| Gray copper.....            | .....      | .....           | .....                     | .....        | .....        | .....              | .....  | As given for arsenopyrite. In either case the buttons may need rescorifying to remove impurities before cupellation.  |
| Iron pyrite.....(1)         | 2          | 3               | 2                         | 3½           | .....        | 10                 | salt   | Roast, and add 2 }<br>A. T. silica. }<br>Silica, 1½ A. T. }<br>Potassium cyanide, 2½ A. T. }<br>Moderate fire. }<br>For ores containing but little pyrites use one of the charges given for a pure ore, with the addition of a few nails or wires. This method of desulphurizing is not recommended for ores containing much sulphur or concentrates. |
| " " ..(2)                   | 1          | 2               | 2                         | .....        | 50           | .....              | salt   |   |
| " " ..(3)                   | 1          | 1               | .....                     | .....        | .....        | .....              | salt   |   |
| Copper pyrites.....         | .....      | .....           | .....                     | .....        | .....        | .....              | .....  | Roast with addition of ammonium carbonate and use charges given for iron pyrites. The buttons may require scorifying to remove copper.  |
| Iron oxide.....             | .....      | .....           | .....                     | .....        | .....        | .....              | .....  | See charge (1) under pyrites.<br>Silica 1 A. T. }<br>Silica 1½ A. T. }<br>Scorify the buttons if brittle. Cupel at a low heat near the end, as the button has a tendency to separate into small particles.  |
| Tellurides .....            | ½          | 4               | 1                         | 1½           | .....        | 10                 | salt   |   |
| " low grade                 | 2          | 4               | 2                         | 2            | .....        | 10                 | salt   |   |



TABLE OF CRUCIBLE CHARGES.\*

| Ore.          | Character of the Gangue.      | A. T. Ore. | Gms. of Lead Flux, † | Gms. of Soda Bicarbonate. | Gms. of Litharge. | Gms. Potassium Ferricyanide. | Gms. Nitre. | Gms. Silica. | Gms. Argol. | Loops of Iron Wire. | Gms. Borax-glass. | Cover. | Remarks.   |
|---------------|-------------------------------|------------|----------------------|---------------------------|-------------------|------------------------------|-------------|--------------|-------------|---------------------|-------------------|--------|--|
| Oxidized...   | Neutral, no Pb....            | ½          | 30                   | .....                     | 25                | .....                        | .....       | .....        | .....       | .....               | .....             | borax  | If cover of salt is used in place of borax, add 3 to 5 gms. borax-glass. |
| Quartz.....   | No bases.....                 | ½          | .....                | .....                     | 75                | .....                        | .....       | .....        | 2           | .....               | .....             | borax  | Special method. If oxide iron is present, add soda in proportion.        |
| Quartz.....   | No bases.....                 | ½          | 30                   | 30                        | 20                | .....                        | .....       | .....        | .....       | .....               | .....             | salt   | If gangue is oxide or carbonate of iron, add 2 to 3 gms. of argol.       |
| Oxidized..... | Basic, no Pb.....             | ½          | 30-40                | .....                     | 20                | .....                        | .....       | 15           | .....       | .....               | .....             | borax  | Borax-glass may be substituted for some of the silica.                   |
| Oxidized..... | Basic, with BaSO <sub>4</sub> | ½          | 40                   | 20                        | 25                | .....                        | .....       | 15           | .....       | 2                   | .....             | borax  | Heat gradually until mass subsides.                                      |
| Galena.....   | Lead 84 per cent...           | ½          | 20                   | .....                     | .....             | 10                           | .....       | .....        | .....       | .....               | .....             | salt   | Litharge is added according to the lead contents of the ore.             |
| Galena.....   | Silicious Pb 42 per cent..... | ½          | 15                   | 20                        | 20                | .....                        | 5           | .....        | .....       | .....               | .....             | salt   |  |

\* Furman's Manual of Assaying.

† Lead flux, p. 26, under 10.

TABLE OF CRUCIBLE CHARGES—(Continued).

| Ore.             | Character of the Gangue.    | A. T. Ore.    | (Gms. of Lead Flux. | (Gms. of Soda Bicarbonate. | Gms. of Litharge. | Gms. Potassium ferrocyanide. | (Gms. Nitre. | Gms. Silica. | Gms. Argol. | Loops of Iron Wire. | Gms. Borax-glass. | Cover. | Remarks.   |
|------------------|-----------------------------|---------------|---------------------|----------------------------|-------------------|------------------------------|--------------|--------------|-------------|---------------------|-------------------|--------|--|
| Lead carbonate   | Neutral Pb 40 per cent..... | $\frac{1}{4}$ | 30                  | 10                         | 15                | ..                           | ..           | ..           | ..          | ..                  | ..                | borax  | Litharge added according to the lead contents of the ore.  |
| Iron pyrites.... | None.....                   | $\frac{1}{2}$ | .....               | 35                         | 30                | ..                           | 5            | 15           | ..          | 6                   | ..                | borax  | Collect matte, if any, and scorify with lead button.   |
| Copper pyrites   | Iron pyrites .....          | $\frac{1}{2}$ | .....               | 35                         | 30                | ..                           | 5            | 15           | ..          | 6                   | ..                | borax  | Collect matte and scorify with lead button. If button is hard, add test-lead.                            |
| Lead matte.....  | .....                       | $\frac{1}{2}$ | 15                  | 30                         | 20                | ..                           | 5            | 15           | ..          | 5                   | ..                | borax  | Special method is preferable.  |
| Copper matte ..  | .....                       | $\frac{1}{2}$ | 15                  | 30                         | 35                | ..                           | 5            | 15           | ..          | 5                   | ..                | borax  | If button is hard or brittle, scorify with lead. Scorification preferable.                               |
| Tellurides. .... | Silicious.....              | $\frac{1}{2}$ | 30                  | 30                         | 40-80             | ..                           | ..           | ..           | ..          | ..                  | ..                | salt   | Special method is preferable. If button is hard or brittle, scorify with lead. Scorification preferable. |
| Tellurides.....  | Silicious.....              | $\frac{1}{2}$ | .....               | 15                         | 80                | ..                           | ..           | ..           | 2           | ..                  | ..                | salt   | Special method.  |
| Arsenical.....   | .....                       | $\frac{1}{2}$ | .....               | 15                         | 30                | 17                           | ..           | ..           | ..          | ..                  | ..                | salt   | Scorify button. Scorification assay is preferable.   |
| Slags.....       | .....                       | 1             | 20                  | 40                         | 10                | ..                           | ..           | ..           | ..          | ..                  | 10                | .....  | If slag contains matte, add loop of iron wire.   |

SCORIFICATION CHARGES.

| Ore.                   | A. T. Ore.     | A. T. Test-lead. | Grams Borax-glass. | Remarks.   |
|------------------------|----------------|------------------|--------------------|--|
| Quartz. ....           | $\frac{1}{5}$  | $1\frac{1}{2}$   | 0.20               |  |
| Copper pyrites. ....   | $\frac{1}{10}$ | $2\frac{1}{2}$   | 0.50               |  |
| Copper matte.....      | $\frac{1}{10}$ | 3                | 1.50               | Or 1.5 grams silica.   |
| Gray copper....        | $\frac{1}{10}$ | 2                | 0.40               |  |
| Iron pyrites.....      | $\frac{1}{4}$  | 3                | 1.40               | Use litharge in place of lead in proportion to the amount of sulphur present.                        |
| Iron oxide.....        | $\frac{1}{5}$  | $1\frac{1}{2}$   | 1.50               | 3 grams silica; vary according to amount of silica in ore.   |
| Galena.....            | $\frac{1}{2}$  | $1\frac{1}{2}$   | 3.00               | Use wire or nail in scorifier. Heat gently.  |
| Carbonate.....         | $\frac{1}{5}$  | 2                | 4.00               |  |
| Chloride.....          | $\frac{1}{5}$  | $1\frac{1}{2}$   | 1.00               | Low heat until covered, then raise heat.   |
| Blende.....            | $\frac{1}{5}$  | 3                | 1.00               | High temperature, and care in assaying.  |
| Arsenic and antimony.  | $\frac{1}{5}$  | 4                | 1.50               | May need several rescorifications. Powdered charcoal aids fusion.                                    |
| Telluride.....         | $\frac{1}{10}$ | 2                | 0.50               | Sprinkle $\frac{1}{16}$ A. T. litharge over the charge. May need several rescorifications with lead. |
| Native Au and Ag.. . . | $\frac{1}{10}$ | $1\frac{1}{2}$   | 0.30               |  |

In the treatment of ores containing sulphur, arsenic, antimony, and tellurium, a preliminary roasting can be made; or they can be heated gently in the scorifier until roasted. Litharge can be used to advantage in all unroasted sulphuret ores.

## SCORIFICATION CHARGES.\*

| Ore $\frac{1}{10}$ A. T.           | Grams of Test-lead. | Grams of Borax-glass. | Remarks.  |
|------------------------------------|---------------------|-----------------------|---|
| Galena.....                        | 15-18               | up to 0.5             |   |
| Galena with blende and pyrite..... | 20-35               | 0.4-0.8               |   |
| Iron pyrite.....                   | 30-45               | 0.3-0.8               |   |
| Arsenical pyrite.....              | 45-50               | 0.3-1.5               | High temperature. Addition of litharge helps assay.   |
| Gray copper.....                   | 35-48               | 0.3-0.5               | Low temperature.  |
| Blende.....                        | 30-45               | 0.3-0.6               | High temperature. Addition of oxide of iron helps assay.                                    |
| Copper ores and mattes             | 35-40               | 0.3-0.5               | Low temperature. If necessary, the button should be rescorified with lead.                  |
| Lead mattes.....                   | 25-35               | 0.5-1.0               |   |
| Furnace accretions.....            | 25-50               | 0.3-1.5               |   |
| Tellurides.....                    | 50                  | 0.3                   | Add a cover of litharge and rescorify the button.   |
| Silicious.....                     | 25-30               |                       |   |
| Basic.....                         | 25-30               | 0.5-2.0               | If the ore contains much lime or magnesia the addition of sodium carbonate helps the assay. |
| Basic with barium sulphate.....    | 25-30               | 0.5-1.5               | Addition of sodium carbonate helps assay.   |
| Lead carbonate.....                | 10-15               | up to 0.5             |   |
| Speisse.....                       | 30-60               | 0.3-0.5               | High temperature. Rescorify the button with lead if necessary.                              |

\* Furman's Manual of Assaying.

INFLUENCES OF BASE METALS ON CUPELLATION.

|                     | Scoria.*         | Stains Cupel.            | Remarks.   |
|---------------------|------------------|--------------------------|--|
| Iron.....           | Brown.           | Brown.                   | The oxide is not easily fusible with lead oxide. If much iron is present, the button may "freeze." Add lead and raise the temperature. In general, these remarks apply also to tin, nickel, cobalt, copper, and platinum. See remarks on iron. |
| Tin.....            | Gray.            | Gray.                    |  |
| Copper.....         |                  | Green to blackish green. |  |
| Zinc.....           | Pale yellow.     | Pale green.              | Also carries much gold and silver into the cupel. Usually not completely removed from the bead. When much copper is present, a rose-colored coat of copper oxide forms on the outside of the cupel.  |
| Nickel and cobalt.. | Dark green.      | Green.                   | Button is slightly crystalline. Burns with a blue flame, and volatilizes, carrying gold and silver with it.  |
| Manganese.....      | Dark.            | Black.                   | Button is crystalline.   |
| Arsenic.....        | Yellowish white. | .....                    | Corrodes the cupel.  |
| Antimony.....       | Yellow.          | .....                    | Spirits. Volatilizes, carrying gold and silver with it. Remove by scorification, if much is present.   |
| Aluminum.....       | Gray.            | .....                    | Spirits. Volatilizes, carrying gold and silver with it. Remove by scorification, if much is present. Causes the cupel to crack.  |
| Chromium.....       | Brick-red.       | Brick-red.               | Retards cupellation.   |
| Tellurium.....      | .....            | Yellow.                  | Retards cupellation.   |
| Titanium.....       | .....            | Deep orange.             | Causes loss by volatilization, and causes subdivision of the bead.   |

\* Scoria may entangle lead, and thus occasion loss, especially if the cupel is disturbed in such a way as to bring lead in contact with the scoria.

## CHAPTER VII.

### AMALGAMATION AND CHLORINATION TESTS.

Amalgamation and chlorination tests are usually intended to give an approximate indication of the percentage of gold and silver that can be extracted by these methods on a working scale.

*Amalgamation Test.*—Pulverize about 5 lbs. of ore fine enough to pass through a 40-mesh sieve. Sample it down to about 1 lb. (see 3; and 1 under 12). Pulverize this sample fine enough to pass through an 80-mesh sieve, and assay it in the regular way. Mix the remaining ore and weigh out 3 lbs. and put  $\frac{1}{4}$  lb. of it into each of the twelve bottles on the shaking-frame (Fig. 37). Add sufficient water to



each bottle to make the ore of the consistency of very thin mud. Add about  $\frac{1}{2}$  oz.




FIG. 37.

of clean mercury to the contents of each bottle, and run the frame at a high speed for

an hour or more. Then empty the bottles into a miner's pan, and wash the tailings into another pan or tub. Pan out the mercury and the concentrates (particles of gold that will not amalgamate, sulphurets, etc.). Dry the concentrates, weigh, and assay them. Dry the tailings and assay them. Retort the mercury, or squeeze it through a clean buckskin, put the amalgam left in the buckskin into a porcelain crucible, and drive off the mercury by heating at first gently and finally to redness. Collect the gold, wrap it in lead-foil and cupel. Small amounts of amalgam can be treated with nitric acid, which dissolves the mercury and leaves the gold.

|  |                               |
|--|-------------------------------|
| Ore assayed . . . . .                        | 3 ozs. gold per ton           |
| Amount of ore taken for amalgamation..       | 3 lbs                         |
| Assay value for 3 lbs. of this ore . . . . . | 2.16 grains gold *            |
| Gold extracted by amalgation from 3 lbs.     | 1.36 grains gold              |
| This corresponds to a yield of . . . . .     | 63 per cent of<br>assay value |
| Concentrates from 3 lbs. . . . .             | 3 ozs                         |

\* See tables on page 136.

|   |                            |
|---|----------------------------|
| One ton would give. ....                      | 125 lbs                    |
| Sixteen tons of ore would give.....           | 1 ton of concen-<br>trates |
| Concentrates assayed per ton concentrates     | 16.48 ozs.                 |
| The 125 lbs. in a ton of ore would give... .. | 1.03 ozs.                  |
| Tailings assayed.....                         | 0.09 oz.                   |

The silver can be calculated in the same way.

*Retorting.*—The mercury is usually squeezed through a buckskin and the amalgam put into a retort (Fig. 38), which has




FIG. 38.

been rubbed with chalk on the inside. The amalgam should not be put into the retort in lumps, nor pressed down. Lute the lid on with a paste of flour, and fasten the clamp. Do not fill the retort more than about three-

fourths full. Apply a low heat at the top and gradually increase the heat to redness. After no more mercury comes over, increase the temperature to a cherry-red heat. During the heating, the condensing-pipe must be kept cool by keeping water running over it. The end of the pipe is usually placed in water. If the condensing-pipe sucks water at any time, it must be immediately lifted out of the water to prevent the water from being sucked into the retort and thus cause an explosion. It is safer to attach a canvas or rubber bag to the end of the pipe in the water.

An amalgamation test can be made on a smaller scale by shaking, in a bottle, a pound of ore with an ounce of mercury. The preparation of the ore and the other operations are the same as already explained.

*Chlorination Test.*—Sample and assay the ore as directed under amalgamation assay. Weigh out one pound of the ore and roast it. After it is cold, moisten the ore

sufficiently to make it cohere slightly when compressed in the hand. Put it into a wide-mouth bottle that has an opening at the bottom. The bottle should not be over half full. Pass a stream of chlorine into the bottle through the opening at the bottom. When chlorine begins to escape at the top, close the bottle and pass the chlorine a while longer. Then close the lower opening, and let it stand twenty-four hours. If at the end of that time, chlorine is still in excess, leach the ore with hot water until the filtrate gives no reaction for chlorine. Dry the residue and assay it. From the difference between this and the first assay, the approximate percentage of extraction can be calculated. The gold in the solution can be precipitated with ferrous sulphate. Collect the precipitate and cupel.



## CHAPTER VIII.

### THE ASSAY OF ORE CONTAINING COARSE METAL.

WHEN ore contains scales of gold or other coarse metal that will not pass the sieve, it may be assayed by one of the following methods:

1. Weigh (in grams) the pulp that passes the sieve, and determine its value by crucible or scorification assay in the regular way. Weigh (in grams) also the scales or other coarse metal, and determine its value in the same way. If the scales consist of gold and silver only, wrap them (or an equal part of them) in lead-foil, and cupel them in the regular way. If the gold only is to be determined, add the necessary silver to insure separation (see pp. 21 and 37) before cupelling the scales.



*Example.*—Suppose the pulp that passed the sieve weighed 112.664 grams, and the coarse metal weighed 4 grams. 1 assay ton of the pulp yielded 0.002 gram gold.  $112.664 \div 29.166$  (grams in one assay ton) = 3.86 assay tons in the pulp that passed the sieve. If 1 assay ton gave 0.002 gram gold, 3.86 assay tons would give  $3.86 \times 0.002$  gram = 0.00772 gram gold. The 4 grams coarse metal gave 0.014 gram gold.  $0.00772 + 0.014 = 0.02172$  gram gold in the whole sample.

112.664 grams that passed the sieve + 4 grams coarse metal = 116.664 grams, the weight of the whole sample.

$116.664 \div 29.166 = 4$  assay tons in the whole sample, which yielded 0.02172 gram gold. 1 assay ton ( $0.02172 \div 4$ ) will give 0.00543 gram, which = 5.43 ozs. Troy to 1 ton ore of 2000 lbs. Avoirdupois (see assay ton weights, p. 9). The silver can be calculated in the same way.

2. If the coarse metal consists of copper or silver, dissolve it in nitric acid; if it consists of gold, dissolve it in aqua regia ( $3\text{HCl} + \text{HNO}_3$ ). Evaporate the solution to a small bulk, and add it to the ore that passed the sieve in such a way that it will not run or soak through to the bottom. Dry the sample at a temperature not above  $100^\circ \text{C}$ . Then pulverize it again, pass it through the sieve, and mix it *thoroughly*. Assay it in the regular way.

If copper is present, assay it by one of the methods given in Chapter IX.

3. Place some of the pulverized ore on the bucking-board, or in a grinder, add the scales, and grind hard until the scales pass the sieve. Mix the ore thoroughly, and assay it in the regular way.

By this method it is difficult to get assays that agree closely.

## CHAPTER IX.

### THE ASSAY OF COPPER ORES AND COPPER-BEARING MATERIALS FOR GOLD AND SILVER.

THE operations in making these assays are not described in detail as the student, if he has mastered the preceding chapters of this book, is familiar with the operations of the crucible and scorification assays. The crucible and scorification charges for the different gangue materials are also given on preceding pages.

Ores and materials containing copper may be assayed by one of the following methods:

1. The gold can be determined by crucible assay, if the percentage of copper is not above about 15 per cent.

Take  $\frac{1}{2}$  A. T. ore, or  $\frac{1}{4}$  A. T., if the percentage of copper is high. Add silica, and, if

sulphur is present, roast the ore, cool, add ammonium carbonate, and heat (see roasting, and crucible charges for ores containing copper). Scorify the button with silica, test-lead, and borax to remove copper, and cupel.

If the ore is low grade, make a number of assays, and scorify the resulting buttons to remove copper, and to reduce them to the proper size for cupelling.

Determine the silver by scorification assay. If the ore is low grade, make a number of assays, and scorify the buttons as directed above (see scorification charges for copper ore).

2. Ores and mattes containing much more than 15 per cent copper can be assayed by the scorification method (see scorification charges for ores and mattes containing copper). If the percentage of copper is high, take  $\frac{1}{20}$  A. T., and make from 3 to 10 scorifications. Scorify the resulting buttons with

a little silica, test-lead (if they contain much copper, or if the amount of lead is small), and a little borax.

3. The combination wet-and-dry method is, in general, as follows: 1 A.T. is treated with nitric acid until all the copper is dissolved. The red fumes are expelled by boiling, after which the solution is filtered. If ore is treated, the residue is brought on to the filter, washed, and dried. Take the residue from the filter, burn the filter-paper in a porcelain crucible, and add the ash to the residue, flux and assay as usual. Add sufficient normal salt (NaCl) solution to the filtrate to precipitate the silver. Avoid an excess, as silver chloride is soluble in salt solution. Allow the silver chloride to settle, then filter, wash the silver chloride on to the filter, put the filter-paper with the silver chloride into a scorifier, burn the filter in front of the muffle at a low temperature, add test-lead, scorify, and cupel.

If copper borings are assayed, the residue, silver chloride, and both filter-papers can be put into the same scorifier (the papers burned) and scorified.

There are various modifications of this method :

(1) *Prof. Cabell Whitehead's Method.\**  
—Dissolve 1 to 4 A. T. in a large beaker (500 c.c. capacity), by the gradual addition of strong nitric acid ; drive off red fumes by heating in sand-bath ; add 50 c.c. saturated solution of lead acetate ; stir ; add 1 c.c. dilute sulphuric acid, and allow lead sulphate to settle. Filter ; wash with cold water, dry in scorifier ; burn filter-paper ; scorify with test-lead ; cupel, weigh, and part as usual.

Dilute the filtrate to 1000 c.c. : divide in halves of exactly 500 c.c. ; add to each saturated solution of sodium bromide so long as a precipitate forms. A large precipitate of

---

\* Transactions of the American Institute of Mining Engineers, March, 1895.



lead bromide collects and envelopes the silver bromide permitting immediate filtering without loss. Filter; wash with cold water; dry filters and precipitates; brush into small crucibles; mix each with three times its weight of carbonate of soda and some flour or argol as reducing agent; cover with borax-glass; fuse for lead buttons; cupel and weigh. The two results should agree closely.

(2) *Dr. Godshall's Method.*\*—Dissolve 1 A. T. of copper borings in dilute nitric acid (90 c.c. strong acid to 100 c.c. water). Evaporate the solution to expel free nitric acid, add 20 c.c. sulphuric acid, and continue the evaporation. Add hot water to take up the copper salts, dilute to about 800 c.c., and allow to cool. Then pass a rapid stream of sulphuretted hydrogen into the solution for about two minutes. Stir the liquid containing the precipitate, then allow the precipitate

---

\* Transactions of the American Institute of Mining Engineers, February, 1900.

to settle about half an hour, then filter rapidly.

Dry the copper sulphide containing the gold and silver, burn the filter in a scorifier, and scorify the residue with 50 grams test-lead.

When nitric acid acts on copper, nitrous acid is formed. Some gold is dissolved, in a hot solution, by the combined action of nitric acid and nitrous acid. By the combined wet-and-dry method, as given above, the average percentage of the loss of gold is high. For the determination of gold in copper-bearing materials, the scorification method (see 2 above) gives much better results.

(3) Mr. W. Randolph Van Liew has evolved a method\* by which he claims an average gain of 6.75 per cent of gold in favor of his method, as compared with the

---

\* The *Engineering and Mining Journal*, April 21st and 28th, 1900.

usual wet-and-dry method. His method is substantially as follows:

Take 1 A. T. copper, treat with 350 c.c. very cold water, and 100 c.c. nitric acid (sp. gr. 1.42), and set the beaker in a cool place (temperature should be kept down to 15° or 16° C.). At the end of 18 or 20 hours, add sufficient nitric acid to dissolve the remaining copper (amount of acid will vary from 0 c.c. to 30 c.c. nitric acid, sp. gr. 1.42). At the end of 24 to 26 hours, the solution of copper is complete. Remove the oxides of nitrogen by compressed air. Insert the pointed end of a pointed glass tube into the solution through which pass air into the solution, by means of a blower or other apparatus, until the red fumes are removed, which takes from 20 to 30 minutes. No heat is applied at any stage of the process.

Add to the cold solution a slight excess (of from 2 c.c. to 4 c.c.) of normal NaCl solution. Experiments have shown that no

difference was made whether the gold was filtered off before or after the addition of normal NaCl solution.

Allow to stand over night, then filter, wash the entire contents to the point of the filter-paper, cover with from 4 to 6 grams test-lead, and, after the filter-paper has drained, place it in a  $2\frac{1}{2}$ -inch scorifier, in the bottom of which there is about 1 gram test-lead.

Dry and burn the paper in a muffle at a temperature below incipient redness. At the end of the yellow flame of the paper, remove the scorifier, and allow the charred paper to burn outside the furnace. By this slow combustion at a low temperature, loss of silver, by its reduction from silver chloride, is avoided.

At the end of about 20 minutes the paper will have burned. Now add from 3 to 4 grams litharge, and from 3 to 4 grams borax-glass.

If all the copper has been washed out, and there are no impurities, no scorification is necessary. The operation is simply to melt and collect the gold and silver, after which the scorifier may be poured. Cupel the button at a temperature giving heavy litharge feathers, and allow to blick at the same temperature.

The time of operation is 48 hours.

Mr. Van Liew reported 6 tests, by this method, which showed a loss of silver of from 1.2 to 2.2 per cent, or an average loss of silver of 1.7 per cent. Eighteen tests on c.p. gold showed a loss of gold of 0.00 per cent to 0.50 per cent, or an average loss of gold of 0.13 per cent.

L. of C.

## CHAPTER X.

### THE DRY ASSAY OF MERCURY.

THE dry assay of mercury is effected in various ways: (1) The ore is pulverized and mixed with reducing agents, and then put into a retort, combustion-tube, or other distilling apparatus. The mercury is then driven off by heat, condensed, collected, and weighed. If the ore is rich and a large amount of it is taken, this method may give approximately accurate results. (2) Better results are obtained by receiving the mercury on gold-foil with which the mercury amalgamates, but gold is expensive. After each assay, the mercury must be driven out of the gold-foil, which usually occasions a loss of gold. After a number of determinations,



the gold must be remelted and rolled out again.

On account of these and other objections to the use of gold, Mr. Richard E. Chism employs silver as a recipient for the mercury. The following is condensed, with some changes, from his article\* describing his method:

#### Apparatus† and Flux.

*Heating Apparatus.*—A glass alcohol-lamp can be used.

*Retort or Crucible.*—Use a glazed white clay (or porcelain) crucible, in the form of a truncated cone, about 2 centimeters outside diameter at the bottom, and 3.5 centimeters diameter at the mouth; height about 4.5 cen-

---

\* Transactions of the American Institute of Mining Engineers, October, 1898.

Mr. Chism claims as original the use of silver for receiving mercury (though this was suggested before), and the use of a separate vessel to cool the receiving surface by contact.

† See Fig. 39.




FIG. 39.—APPARATUS FOR MERCURY-ASSAY ONE-HALF  
ACTUAL SIZE.

*A*, base of retort-stand. *B*, spirit-lamp. *C*, retort or annealing-cup. *D D*, retort stand ring, which serves as support to the apparatus. *E E*, tin shields. *F F*, silver-foil for receiving the mercury. *G*, cooling-cup.

timeters. The mouth of the crucible should have an even surface.

*Shield.*—To prevent the direct heating of the upper part of the crucible and silver-foil, use a circular tin shield about 13 centimeters in diameter, with a hole in the center large enough to pass the crucible partly through, leaving about 1 centimeter of the crucible above the shield.

*The Recipient.*—Use a piece of pure silver-foil (rolled silver) about 5 centimeters square, and about 0.02 millimeters in thickness, on which to receive the mercury. It should be large enough to cover the crucible and leave a margin all round of about one-half centimeter.

*Cooling-cup.*—For cooling the silver-foil, use a silver dish of a wide pattern like an evaporating-dish. Silver is a good heat-conductor. A copper dish could be used. The bottom of the dish should be a little larger than the mouth of the crucible. Keep the

bottom of the dish polished to enable you to discover any mercury that might soak through the silver-foil. Should this happen, drive off the mercury from the dish by heat, and repeat the assay with new silver-foil and less ore.

*Flux.*—Use iron filings, the finer the better. They should pass a 60-mesh sieve. Remove most of the grease with strong alcohol, and then heat them to redness for some time in a muffle. Then keep the filings in a glass bottle with a rubber stopper.

#### To Make the Assay.

Take from one-half to one gram of the ore, prepared as directed under 3. If the ore is very rich, take less. Thoroughly mix the ore in the crucible with 5 grams of the prepared iron filings, and put about one gram of the iron filings on top of the charge as a cover. Now hang the *crucible*, by its tin shield, from the ring of a ring-stand. Carefully smooth the *silver-foil* (see The Recipient above), and

ignite it in the flame of an alcohol-lamp. Care must be taken not to overheat the foil, or it will fuse. Cool the foil in a desiccator (Fig. 40), and then weigh it accurately on an




FIG. 40.

analytical balance. Press it gently on the mouth of the crucible until it assumes the shape of the mouth of the crucible.

Place the *cooling-cup* upon the silver-foil on top of the crucible, and fill the cooling-cup with cold water (ice-water, if at hand),

Place the *alcohol-lamp* under the crucible, and arrange it to give a flame about 4 centimeters high, which shall barely spread out at its point over the central part of the bottom of the crucible.

Continue the heating from 10 to 15 minutes. Ten minutes is too short for most ores, and anything over 15 minutes is apt to lead to loss of mercury.

If ice-water is not used, it may be necessary to renew the water in the cooling-cup once or twice during the heating.

When the heating is at an end, allow the crucible and contents to cool at least five minutes. When the silver-foil is removed, a distinct mercurial stain will be seen upon its lower surface, if there was the slightest trace of mercury in the ore.

Convey the foil (under cover to avoid dust) to the balance, and weigh it. The increase in weight of the foil shows the amount of mercury on the foil.

In order to check the first determination, and make sure that all the mercury has been collected, place the silver-foil on the crucible again, and heat the same charge about 10 minutes more, allow to cool, and weigh again.



If the weight is constant, or if there is a slight decrease in weight, the amount of mercury obtained by the first weighing may be considered correct. If more mercury has been collected on the second weighing, repeat the determination with a new charge, and heat a longer time—five or ten minutes longer than the first time.

The foil can be preserved for future reference, or the mercury can be driven off by carefully heating it in an alcohol flame; then the foil can be used for another determination.

Polish the foil, if it is not bright, and carefully anneal, cool, and weigh it just before making each assay, as directed above.

*Failures.*—Failures may arise from too high or too long heating, from the foil being badly adjusted to the mouth of the crucible, or from the cooling apparatus not being properly managed.

## CHAPTER XI.

### VOLUMETRIC DETERMINATION OF COPPER.

MR. ALBERT H. LOW, assayer and analytical chemist, of Denver, Colorado, has modified the cyanide method and the iodide method for the determination of copper. He has sent me the following descriptions of these methods as modified by him :

#### The Cyanide Assay for Copper.

*Standardization of the Solution.* — The standard solution should contain about 21 grams of pure potassium cyanide per 1000 c.c. Determine the exact standard as follows :

Dissolve about 0.200 gram, accurately weighed, of pure copper-foil in 5 c.c. of strong nitric acid. Use a flask of about 250

c.c. capacity. Without troubling to boil off the red fumes, add about 80 c.c. of water and 10 c.c. of strong ammonia water. Cool the mixture to the ordinary temperature. Titrate with the cyanide solution, slowly and cautiously, so as to allow sufficient time for the fading of color due to each addition. When the blue color has become perceptibly weaker, but is still fairly strong, dilute the solution so that the final bulk will be about 150 c.c. Now finish the titration by adding the cyanide in a slow and regular manner, finally one drop at a time until the blue tint is entirely discharged. The exact end-point is best observed by the aid of a vertical white background. From the amount of cyanide required, calculate the copper value per c.c.

The accuracy of all subsequent work with the standard solution depends upon the operator's ability to duplicate the essential conditions of the final additions of cyanide. These are temperature, bulk of solution, and speed

of working. Up to the point where the amount of cyanide added is insufficient to nearly discharge the color on long standing, the manner of adding it appears of no consequence; and the assay that has thus stood may be resumed and finished without detriment. The reaction proceeds rather slowly, and towards the end its speed is usually exceeded by that of the operator. It is therefore necessary, in finishing the titration, to proceed in a deliberate, methodical manner that can be duplicated in all subsequent work.

*Assay of Ores, etc.*—Treat 0.5 gram in a flask of about 250 c.c. capacity with about 6 c.c. of strong nitric acid. Boil gently nearly to dryness, and then add 5 c.c. of strong hydrochloric acid, and again heat until all soluble matter is taken up. Now add 5 c.c. of strong sulphuric acid, and boil until the white fumes are freely evolved.

Time may be saved and bumping avoided

by manipulating the flask in a holder over a naked flame.

Allow to cool, add 20 c.c. of cold water, and heat to boiling. When an ore contains much iron, an insoluble anhydrous sulphate is apt to be present at this stage, which will only slowly dissolve in the warm dilute acid, meanwhile remaining more or less in suspension with a milky appearance. This anhydrous sulphate retains copper. Do not proceed to filter, therefore, but keep the mixture warm, with occasional agitation, until the liquid clears and the residue appears normal. This may take several minutes. Finally filter, wash with cold water, and collect filtrate in a beaker about two and one-half inches in diameter. There should be about 75 c.c. of combined filtrate and washings.

Place in the beaker a piece of stout sheet aluminum about five and one-half inches long and five-eighths of an inch wide, bent into a triangle so as to stand on edge. The same

triangle will last for many assays. Add one drop of a mixture of equal parts of strong hydrochloric acid and water, cover the beaker, and heat to boiling.

A strong action is liable to occur unexpectedly, and it is usually necessary to lower the heat when boiling begins. Boil gently for 7 to 10 minutes, and then remove from the heat, and wash down the cover and sides of the beaker with cold water. Now add 15 c.c. of strong sulphuretted hydrogen water. This should produce little or no discoloration. Even though the copper be entirely precipitated, there is still danger of oxidation and loss during the subsequent washing unless sulphuretted hydrogen water be employed.

Pour the solution through a 9 c.m. filter, and rinse on the copper with sulphuretted hydrogen water. Wash once or twice with the same water, and then finish with pure cold water.

The metallic copper on the filter is more or



less mixed with copper sulphide, and there may be a little copper left adhering to the aluminum in the beaker. Pour over the latter 5 c.c. of strong nitric acid, and then wash this into a second beaker, using not over 5 or 10 c.c. of water. Now transfer the filter and copper into the dilute acid, and warm gently until all is dissolved, and the separated sulphur appears clean.

If the ore contains silver, it should be precipitated at this stage by the addition of a single drop of strong hydrochloric acid before the heating. Filter the copper solution into the original flask. Wash the filter thoroughly, but avoid getting the filtrate too bulky. Add 10 c.c. of strong ammonia water to the filtrate, cool to the ordinary temperature, and titrate with the standard cyanide solution precisely as in the standardization. Dilute with water towards the end, if necessary, so as to obtain a final bulk of about 150 c.c.

Should the presence of lead or other impur-

ity cause a milkiness in the blue solution, it is best to filter the mixture, when nearing the end of the titration, through a coarse rapid-running filter. From the number of c.c. of standard cyanide required, calculate the percentage of copper in the ore.

When the amount of silver is known, it need not be removed, but may be allowed for on the basis that  $2\text{Ag}=\text{Cu}$ . 100 ounces of silver per ton of 2000 lbs. will approximately equal 0.10 per cent of copper. Deduct, accordingly, 0.10 per cent of copper for every 100 ounces of silver per ton.

#### Copper Assay by the Iodide Method.

Prepare a solution of sodium hyposulphite containing about nineteen grams of the pure crystals to the liter. Standardize as follows: Weigh accurately about 0.200 gram of pure copper-foil and place in a flask of about 250 c.c. capacity. Dissolve in five c.c. of a mixture of equal volumes of strong

nitric acid (1.42 sp. gr.) and water; and then dilute to about fifty c.c., and boil until the red fumes are thoroughly expelled. This last is a very essential point. Remove from the heat and add a slight excess of ammonia water to the hot liquid. Ordinarily it suffices to add five c.c. of strong ammonia (0.90 sp. gr.). Now add acetic acid in slight excess,—say three c.c. of the 80 per cent acid in all. Cool to ordinary temperature and add three grams of potassium iodide, or five c.c. of a solution containing sixty grams of potassium iodide in 100 c.c. Cuprous iodide will be precipitated, and iodine liberated according to the reaction  $2(\text{Cu} \cdot 2\text{C}_2\text{H}_3\text{O}_2) + 4\text{KI} = \text{Cu}_2\text{I}_2 + 4(\text{K} \cdot \text{C}_2\text{H}_3\text{O}_2) + 2\text{I}$ .

The free iodine colors the mixture brown. Titrate at once with the hyposulphite solution until the brown tinge has become weak, and then add sufficient starch liquor to produce a marked blue coloration. Continue the titration cautiously until the blue tinge

has entirely vanished. When almost at the end, allow a little time after the addition of each drop to avoid passing the point. One c.c. of the hyposulphite solution will be found to correspond to about 0.005 gram of copper. In the assaying of ores, when half a gram is taken, one c.c. of the standard hyposulphite would then equal about one per cent of copper. The reaction between the hyposulphite and iodine is  $2(\text{Na}_2\text{S}_2\text{O}_3) + 2\text{I} = 2\text{NaI} + \text{Na}_2\text{S}_4\text{O}_6$ . Sodium iodide and tetrathionate are formed.

The starch liquor may be made by boiling about half a gram of starch with a little water, and diluting with hot water to about 250 c.c. It should be used cold, and must be prepared frequently, as it does not keep well.

The hyposulphite solution made from the pure crystals and distilled water appears to be quite stable, showing little or no variation in a month, if kept under reasonable conditions.

**Treatment of Ores.**

To half a gram of the ore in a flask of 250 c.c. capacity, add about six c.c. of strong nitric acid, and boil gently nearly to dryness. Then add five c.c. of strong hydrochloric acid and again heat. As soon as the incrustated matter has dissolved, add five c.c. of strong sulphuric acid, and boil until the more volatile acids are expelled, and the fumes of sulphuric acid are coming off freely. This is best done by manipulating the flask in a holder over a naked flame. Allow to cool and add 20 c.c. of cold water, and heat the mixture to boiling. Allow to stand, hot, until any anhydrous sulphate of iron is dissolved, and then filter to remove more especially any lead sulphate. Receive the filtrate in a beaker about two and a half inches in diameter. Wash flask and filter with either hot or cold water and make the volume of the filtrate about seventy-five c.c. Place in



the beaker a piece of sheet aluminum prepared as follows: Cut a strip of stout sheet aluminum five-eighths of an inch wide and about five and one-half inches long, and bend this into a ring so that it will stand upon its edge in the beaker. The same aluminum may be used repeatedly, as it is but little attacked each time. Add one drop of a mixture of equal parts of strong hydrochloric acid and water, cover the beaker and heat to boiling. Allow to boil seven minutes, which will be sufficient to precipitate all the copper in any case, provided the bulk of the solution does not much exceed seventy-five c.c. The aluminum should now appear clean, the precipitated copper being detached or only loosely adhering. Remove from the heat and wash down the cover and sides of the beaker with cold water. There is danger of the finely divided copper being slightly oxidized and dissolved during the subsequent washing. To prevent this, add at once



fifteen c.c. of strong hydrogen-sulphide water. If the amount of the precipitated copper is large, it is best to wash it by decantation, as will be subsequently described; but, for quantities not exceeding say 20 per cent, it is more convenient to proceed as follows: Pour the clear liquid through a nine cm. filter and then wash on the copper with cold  $\frac{1}{2}$  s. water. The beaker and aluminum, which may still retain some adhering particles of copper, are now set aside temporarily. Wash the copper on the filter several times with cold water, and then place the original flask under the funnel. Now pour over the aluminum in the beaker five c.c. of a mixture of equal volumes of strong nitric acid (1.42 sp. gr.) and water, and heat to boiling. Do not prolong the boiling, or the aluminum will be unnecessarily attacked. Pour the hot acid very slowly over the copper on the filter so as to dissolve it all, and then wash beaker and

filter several times. Heat the solution in the flask to boiling and thoroughly boil off the red fumes; then replace the flask under the funnel and pour five c.c. of strong bromine water through the filter. The bromine cleanses the separated sulphur left on the filter, and also insures the highest oxidation of any arsenic or antimony present in the filtrate. If five c.c. are insufficient to impart a permanent tinge to the filtrate, more must be added. Again wash the filter and then boil the filtrate, which usually does not exceed seventy-five c.c. in bulk, to thoroughly expel the excess of bromine. Remove from the heat and add ammonia water in slight excess (ordinarily add five c.c. of strong ammonia), and then acidify with acetic acid. The addition of three c.c. of the glacial acid is usually sufficient. A large excess of acetic acid does no harm, but is not necessary, except in the presence of sufficient arsenic to cause a precipitate of

copper arseniate. This may require considerable acetic acid for its solution. If not dissolved at this stage, it is taken up slowly later on, and the titration may become very tedious before the true end-point is finally reached. Proceed with this acetic acid solution precisely as described in the standardization of the hyposulphite, and calculate the percentage of copper from the amount of hyposulphite required.

With high percentages it is advisable to wash the precipitated copper by decantation as follows: Transfer the liquid and copper in the beaker to the original flask, and set the beaker and aluminum aside temporarily. Decant through the filter and wash the copper perhaps three times by decantation with cold dilute  $\frac{1}{2}$  s. water, using about 20 c.c. each time. Now place the flask under the funnel, heat the five c.c. of acid in the beaker as before, and pour it through the filter. Do not wash for the moment, but remove the

flask, replacing it under the funnel with the beaker, and heat the acid until all the copper is dissolved. Now return the flask under the funnel and proceed with the washing. Boil off the red fumes and continue as described above.

*Notes.*—According to the equation previously given, half a gram of pure copper requires 2.62 grams of potassium iodide. While direct experiment shows this to be apparently true, yet with only the theoretical amount of iodide present the reaction is slow, and in fact does not appear to proceed to completion until during the titration, which is thereby unduly prolonged. It is best, therefore, to use not less than three grams in any case. An excess does no harm. Zinc and silver do not interfere. Lead and bismuth are without effect, except that by forming colored iodides they may mask the approach of the end-point before adding starch. Lead is practically removed as sul-

phate by the first filtration. If bismuth is suspected in appreciable amount, simply add the starch earlier in the titration. Arsenic and antimony when fully oxidized as described have no influence. The return of the blue tinge in the titrated liquid after long standing is of no significance, but a quick return, which an additional drop or two of the hyposulphite does not permanently destroy, is usually an evidence of faulty work.

## CHAPTER XII.

### VOLUMETRIC DETERMINATION OF LEAD.

Some assayers check their fire-assays of lead by a wet method. For the convenience of those who desire a rapid method to check their fire-assays, the ammonium molybdate\* method is here given.

This method is based upon the fact that ammonium molybdate, when added to a hot solution of lead acetate, will give a precipitate of molybdate of lead ( $\text{PbMoO}_4$ ), which is insoluble in acetic acid. Any excess of ammonium molybdate will give a yellow color with freshly prepared solution of tannin.

*Indicator.*—A freshly prepared solution of 1 part tannin in 300 parts water.

*Standard Solution.*—The standard solution

---

\* H. H. Alexander, The Engineering and Mining Journal, April 1st, 1893.



of ammonium molybdate is prepared by dissolving 9 grams of ammonium molybdate in 1000 c.c. of water. One c.c. of this solution will equal about 0.01 gram lead. If the solution is not clear, it can be made so by adding a few drops of ammonium hydrate.

*Standardizing.*—Weigh out 0.300 gram of pure sulphate of lead, and dissolve it in hot ammonium acetate; then acidify with acetic acid, and dilute with hot water to 250 c.c. Heat to boiling, and add from a burette the molybdate solution, prepared as above mentioned, until all the lead is precipitated as a white precipitate. This is ascertained by placing drops of tannin solution upon a porcelain plate, and then to these drops is added a drop of the solution tested, after each addition of ammonium molybdate. As long as the lead is in excess, no coloration is produced; but as soon as the molybdate is in excess, a yellow color is produced with the tannin ( $0.300 \text{ gram PbSO}_4 \times 0.68317 = 0.20495$

gram Pb). The solution in the beaker should be stirred after each addition of molybdate solution before the drop-test is made. From the number of molybdate solution used, the value of one c.c. is calculated in the usual way.

*Assay.*—To determine the lead in ore or other material, weigh out 0.5 or 1.0 gram of the substance, according to the percentage of lead. If the substance contains 30% or more lead, 0.5 gram will be sufficient. Treat the sample weighed out in a porcelain casserole with 15 c.c. strong nitric acid and 10 c.c. strong sulphuric acid. Heat until all the nitric acid is expelled, which is indicated by fumes of sulphuric anhydride coming off; then allow it to cool, and dilute with cold water; stir, then boil until all soluble sulphates are brought into solution. Now filter, leaving as much of the precipitate in the casserole as possible. Now wash twice with hot dilute sulphuric acid and once with cold water. The sulphate of lead remaining in the

casserole is next dissolved with hot ammonium acetate; pour the hot solution on the filter and allow it to run into a clean beaker. This operation is repeated until all the sulphate of lead is dissolved. Wash out the casserole thoroughly with hot water into the filter. Acidify the solution with acetic acid, dilute up to 250 c.c. with hot water. Now heat to boiling and run in from a graduated burette the standardized solution of ammonium molybdate until all the lead is precipitated, stirring the solution after each addition of molybdate, and testing a drop of the solution, after each addition of molybdate, on a porcelain plate with the tannin solution. From the number of c.c. of the molybdate solution used, calculate the per cent of lead.

The lead determination can easily be made in 30 minutes.

Arsenic, antimony and phosphorus do not interfere with this method, as they pass through the filter in solution.

## APPENDIX A.

### SUPPLEMENTARY NOTES ON THE ASSAY OF ORES.

*Cupels.*—If the bone-ash used in making cupels is coarse, the cupels will be too porous, and much silver and some gold will be carried into the cupel. If the bone-ash is very fine and the cupels are compressed very hard, they will be too dense, may not absorb the litharge as fast as formed, and will crack in drying, and on becoming saturated with litharge. If the cupels are not compressed hard enough, they will be too porous; if compressed too hard, they will be too dense. The results in these cases are the same as stated above (see also p. 3). Some assayers take one part of wheat flour and mix it thor-

oughly with ten parts of bone-ash before moistening, and compress the cupels hard. On heating the cupels in the muffle before the buttons are dropped into them, the flour burns out, leaving the cupels porous.

From what has been stated, it is evident that cupels should be made of fine bone-ash, and of such hardness that they will absorb the litharge, and as little of the precious metals as possible. A cupel made of fine bone-ash, and of such hardness that, when dry, a fall of two to two and one-half feet will not break it, will absorb very little silver. By filling the cupel-mould about two-thirds full of coarse bone-ash, and the remainder, which forms the bowl of the cupel, with extra fine bone-ash, a cupel can be made that will absorb the litharge, and will absorb very little silver.

Cupels will be stronger and less liable to crack in drying, if a strong solution of sodium or potassium carbonate is used instead of

water to moisten the bone-ash. The bone-ash should not be sufficiently moistened to feel wet (see p. 1).

Cupels should be dried slowly before they are used. If they are put into the hot muffle while moist, they will fall to pieces. If buttons are dropped into the cupels before all the moisture and the gases are expelled, loss may result from spirting.

*Sampling.*—Great care should be taken in taking an average sample of ore. Unless the sampling is properly done, the results of the assay are worthless. Not only should great care be taken in taking an average sample across the vein of ore in the mine at different places, but also in sampling the ore so taken for an assay sample (see p. 29).

*Fluxing and Fusion.*—In the chapter on slags, it has been explained that assay charges are made up of basic and acid substances in such proportions that they will combine and form liquid slags. The general reactions are



indicated, but, as stated on page 49, when so many substances are thrown together, many other reactions take place.

The gangue must be so fluxed that all becomes fusible, or the precious metals cannot be released, and collected in a button of lead in the bottom of the crucible. For example, if ferric oxide,  $\text{Fe}_2\text{O}_3$ , forms part of the gangue materials, the charge must contain sufficient reducing agents to reduce the ferric oxide to ferrous oxide,  $\text{FeO}$ . The ferric oxide would not fuse, but would be entangled or absorbed by the soda or slag, and the gold and silver contained in the ferric oxide would be carried into the slag with it; but, if the ferric oxide is reduced to ferrous oxide, the ferrous oxide unites with the silica, etc., and the compound so formed becomes fusible, and allows the precious metals to drop to the bottom of the crucible by virtue of their greater specific gravities (see also under Corrected Assays).

*Cupellation.*—In the operation called cupellation, the lead is oxidized forming litharge. The other base metals also oxidize. Litharge is fusible at a bright red heat, and, when fused, has the property of dissolving or absorbing oxides of other metals. Bone-ash has the property of absorbing melted litharge, and a certain amount of other oxides that may be dissolved by the litharge. Gold, silver, platinum, and some of the rarer metals, do not oxidize by this operation, and, therefore, are not dissolved or absorbed by the litharge, and hence not carried by it into the bone-ash.

When a large amount of base metals is present, the litharge formed may not be sufficient to carry all the oxides into the cupel. If this is the case, some of the oxides remain on the cupel, known as a scoria. An addition of lead might have carried all the oxides into the cupel. A scoria also forms on the cupel if the lead button is not entirely freed

from slag. The scoria may have entangled some lead which carried the gold and silver. Hence the scoria may contain some of the precious metals, which can be recovered by crucible or scorification assay.

After charging in the buttons, the muffle should be closed until they uncover. The muffle should be hot enough to start a rapid oxidation. Then the temperature should be lowered to form litharge crystals, and the buttons should be allowed to blick at a higher temperature.

The muffle can be cooled by checking the fire, or by putting cold scorifiers, crucibles, or cupels into the part of the muffle that is too hot, replacing them when hot, until the desired temperature is secured.

As loss will result, if the button is moved on the cupel, it is safer to regulate the temperature as here directed, than to move the cupels as directed on pp. 19, 35, and 36.

The assayer should aim to approach these somewhat ideal conditions:

1. To flux the gangue so that every particle of it becomes fusible and forms a liquid slag.

2. To reduce the least amount of lead that will just collect all the gold and silver.

3. To have a cupel that is fine and hard enough to absorb all the litharge, and none of the gold and silver.

4. To oxidize the button in the least time possible, avoiding bad effects of too rapid oxidation.

5. To have the muffle hot enough to start a rapid oxidation, then cool sufficient to form litharge crystals, and allow the buttons to blick at a higher temperature.

*Fire Assay of Lead Ore.*—When the muffle is at a low red heat, put the crucibles with the charges into the muffle, and keep the temperature low enough to prevent spitting. Do not allow the temperature to get above redness, and allow the crucibles to re-

main in the muffle from an hour to two hours. The time will depend somewhat on the proper regulation of the temperature. If the blue flame above the crucibles "jumps," the muffle is too hot, and unless the temperature is immediately lowered, the assay will be defective. After the blue flame ceases, allow the assays to remain in the muffle a short time longer. Just before pouring, the temperature should be raised.

If the muffle is left partly open to watch the working of the assays, the opening in the back part of the muffle should be closed with fire-clay, to prevent a draught, of air through the muffle.

By this method higher results can be obtained than by the method described on page 27.

## APPENDIX B.

### TABLES.

#### Atomic Weights.

|                | H. = 1 |                | H. = 1 |
|----------------|--------|----------------|--------|
| Aluminum.....  | 26.91  | Magnesium..... | 24.10  |
| Antimony.....  | 119.52 | Manganese..... | 54.57  |
| Barium.....    | 136.39 | Mercury..      | 198.49 |
| Boron.....     | 10.86  | Nickel.....    | 58.24  |
| Calcium.....   | 39.76  | Nitrogen.....  | 13.93  |
| Carbon.....    | 11.91  | Oxygen.....    | 15.88  |
| Chlorine.....  | 35.18  | Platinum.....  | 193.41 |
| Chromium,..... | 51.74  | Potassium..... | 38.82  |
| Cobalt.....    | 58.55  | Selenium.....  | 78.58  |
| Copper.....    | 63.12  | Silicon.....   | 28.18  |
| Fluorine.....  | 18.91  | Silver.....    | 107.11 |
| Gold.....      | 195.74 | Sodium.....    | 22.88  |
| Hydrogen.....  | 1.000  | Sulphur.....   | 31.83  |
| Iron.....      | 55.60  | Tellurium..... | 126.52 |
| Lead.....      | 205.36 | Tin.....       | 118.15 |
| Lithium.....   | 6.97   | Zinc... ..     | 64.91  |

#### Troy Weight.

24 grains = 1 dwt.  
 480 " = 20 " = 1 oz.  
 5760 " = 240 " = 12 " = 1 lb. = 22.816 cu. in. of  
 distilled water at 62° Fahr.



**Avoirdupois Weight.**

|            |           |                          |
|------------|-----------|--------------------------|
| 1 drachm = |           | 27.34375 grains Troy.    |
| 16 " =     | 1 oz. =   | 437.5 " "                |
| 256 " =    | 16 " =    | 1 lb. = 1.2153 lb. Troy. |
| 6400 " =   | 400 " =   | 25 " = 1 quarter.        |
| 25600 " =  | 1600 " =  | 100 " = 4 "              |
| 512000 " = | 32000 " = | 2000 " = 80 "            |
|            |           | = 20 cwt. = 1 ton.       |

**Metric, or French Weights.**

|               | Grams.     | Troy Grs. |           |           |
|---------------|------------|-----------|-----------|-----------|
| 1 Milligram = | .001 =     | .01543    |           |           |
| 1 Centigram = | .01 =      | .15432    |           |           |
| 1 Decigram =  | .1 =       | 1.5432    | Troy Ozs. | Troy Lbs. |
| 1 Gram =      | 1. =       | 15.432 =  | .032 =    | .00267    |
| 1 Decagram =  | 10. =      | .....     | .321 =    | .02679    |
| 1 Hectogram = | 100. =     | .....     | 3.215 =   | .26792    |
| 1 Kilogram =  | 1000. =    | ... ..    | 32.150 =  | 2.6792    |
| 1 Myriagram = | 10000. =   | .....     | 26.792    |           |
| 1 Quintal =   | 100000. =  | .... ..   | 267.92    |           |
| 1 Tonneau =   | 1000000. = | .....     | 2679.2    |           |

|               | Avoir Ozs. |   | Avoir Lbs. |
|---------------|------------|---|------------|
| 1 Gram =      | .03528     | = | .0022047   |
| 1 Decagram =  | .3528      | = | .022056    |
| 1 Hectogram = | 3.52758    | = | .22046     |
| 1 Kilogram =  | 35.2758    | = | 2.2046     |
| 1 Myriagram = | .....      |   | 22.046     |
| 1 Quintal =   | .....      |   | 220.46     |
| 1 Tonneau =   | .....      |   | 2204.6     |

.064798 gram = 1 Troy grain.


1 gram = 15.43235 Troy grains.

1 A. T. = 29.166 grams = 450.0999 Troy grains.







 FIRE BRICK




FRONT ELEVATION




HORIZONTAL SECTIONS  
Scale,  $\frac{1}{2}$  In. = 1 Ft.

COAL-BURNING



VERTICAL SECTION



REAR ELEVATION

ASSAY-FURNACE.

[To face page 131.]





# INDEX.

---

## A

|   | PAGE        |
|---|-------------|
| Amalgamation Test .....                       | 82          |
| Ammonium Carbonate, in roasting.....          | 70          |
| Ammonium Molybdate Method for Lead .....      | 124         |
| Assay of Gold and Silver Ores.....            | 10, 24, 61  |
| Corrected Assay.....                          | 70          |
| Notes on Assay of Ores.....                   | 29, 128-135 |
| Assay of Copper Ores for Gold and Silver..... | 91-99       |
| Ores containing Coarse Metals.....            | 88          |
| Copper Materials for Gold and Silver... ..    | 91-99       |
| Copper.....                                   | 108         |
| Cupels.....                                   | 71          |
| Lead.....                                     | 26, 44, 124 |
| Mercury.....                                  | 100         |
| Slags.....                                    | 71          |
| Preliminary Assay.....                        | 63          |
| To make the Assay .....                       | 10          |
| To prepare the Assay.....                     | 5           |
| Assay-ton Weights.....                        | 9           |

## B

|                          |    |
|--------------------------|----|
| Bicarbonate of Soda..... | 47 |
| Borax.....               | 50 |

## C

|   | PAGE                   |
|---|------------------------|
| Charcoal.....                             | 52                     |
| Chlorination Test.....                    | 86                     |
| Copper, Determination of.....             | 108                    |
| Cyanide Assay.....                        | 108                    |
| Iodide Assay.....                         | 114                    |
| Ores, Assay for Gold and Silver.....      | 91-99                  |
| Materials, Assay for Gold and Silver..... | 91-99                  |
| Crucible Charges.....                     | 10, 58, 72, 76, 77, 78 |
| Cupels. ....                              | 1, 128                 |
| Assay of.....                             | 71                     |
| Cupellation.....                          | 17, 34                 |
| Influence of Base Metals on.....          | 81                     |
| Notes on.....                             | 34, 132                |

## D

|   |            |
|---|------------|
| Desulphurization by means of Iron Nails. .... | 65         |
| Determination of Copper.....                  | 108        |
| Gold and Silver.....                          | 10, 24, 61 |
| in Copper Ore.....                            | 91-99      |
| in Copper Matte. ....                         | 91-99      |
| in Copper.....                                | 91-99      |
| in Cupels. ....                               | 71         |
| in Slags .....                                | 71         |

## F

|   |                  |
|---|------------------|
| Fire-assay for Gold and Silver Ores (Crucible) 10, 24, 29, 61<br>(Scorification)..... | 24, 43           |
| Flour.....  | 51               |
| Fluxes.....   | 3, 46, 47, 76-80 |
| Fusion in Crucible.....   | 13               |
| Notes on.....   | 32, 130          |

*INDEX.*

141

PAGE

G

Godshall's Method..... 95

I

Iron, Flux..... 53, 104  
in Assays..... 65

L

Lead, Determination by Fire-assay. .... 26, 44  
by the Wet Method..... 124  
Notes on the Fire assay..... 44, 134  
Fluxes..... 26, 46  
Litharge .. 49

M

Mercury, Assay of..... 100

P

Parting..... 21  
Notes on. .... 37  
Potassium Cyanide... 52  
Potassium Nitrate..... 53

R

Retorting..... 85  
Roasting..... 67  
with Ammonium Carbonate.... 70

S

Salt..... 53  
Samples and Sampling..... 29, 130

|                            | PAGE   |
|----------------------------|--------|
| Scorification Assay.....   | 24     |
| Notes on.....              | 43     |
| Scorification Charges..... | 79, 80 |
| Silica .....               | 51     |
| Slags.....                 | 55     |
| Assay of.....              | 71     |
| Sodium Bicarbonate. ....   | 47     |
| Special Methods.....       | 74     |

## T

|                              |     |
|------------------------------|-----|
| Tables.....                  | 136 |
| Atomic Weights .....         | 136 |
| Avoirdupois Weight.....      | 137 |
| Metric, or French Weights... | 137 |
| Troy Weight.....             | 136 |
| Tellurium Ores.....          | 74  |
| Test-lead.....               | 54  |

## V

|                       |    |
|-----------------------|----|
| Van Liew's Method.... | 96 |
|-----------------------|----|

## W

|                         |    |
|-------------------------|----|
| Whitehead's Method..... | 94 |
|-------------------------|----|

# Notes on Assaying.

BY

PIERRE de PEYSTER RICKETTS, E.M., Ph.D.,

*Formerly Professor of Analytical Chemistry and Assaying,  
School of Mines, Columbia University,*

AND

EDMUND H. MILLER, A.M., Ph.D.,

*Instructor in Analytical Chemistry and Assaying,  
School of Mines, Columbia University.*

*THIRD EDITION, REVISED.*

8vo. 320 pages. Thirty-nine Cuts.  
Cloth, \$3.00.

CONTENTS.—PART I. Introduction. Apparatus. Reagents and Chemicals. Operations.—PART II. Dry or Fire Assays.—PART III. Wet Assays or Analyses.—PART IV. Laboratory Tests on Ores. Assay, Blow-pipe, and Qualitative Schemes.—PART V. Tables, Examples, and References.

---

A

# Manual of Practical Assaying.

By H. VAN F. FURMAN, E.M.

*FIFTH EDITION, REVISED.*

8vo. 475 pages. Cloth, \$3.00.

CONTENTS:—PART I. Introductory.—PART II. Determinations.—PART III. Special Assays and Analyses.—PART IV. Calculations. Tables.—APPENDICES. Appendix A. Melting and Refining Gold Bullion. Appendix B. The Preparation of Pure Gold and Silver. Appendix C. Losses of Gold and Silver in the Fire Assay. Appendix D. Laboratory Tests in Connection with the Extraction of Gold by the Cyanide Process. Appendix E. The Analysis of Refined Copper. Appendix F. The Mechanical Assay of Gold and Silver Ores. Appendix G. The Calculation of Copper-matte Blast-furnace Charges. INDEX.





# SHORT-TITLE CATALOGUE

OF THE  
PUBLICATIONS

OF  
JOHN WILEY & SONS,

NEW YORK.

LONDON: CHAPMAN & HALL, LIMITED.

ARRANGED UNDER SUBJECTS.

Descriptive circulars sent on application.  
Books marked with an asterisk are sold at *net* prices only.  
All books are bound in cloth unless otherwise stated.

## AGRICULTURE.

|  |       |        |
|--|-------|--------|
| Armsby's Manual of Cattle-feeding.....                                 | 12mo, | \$1 75 |
| Downing's Fruits and Fruit-trees of America.....                       | 8vo,  | 5 00   |
| Grotenfelt's Principles of Modern Dairy Practice. (Woll.)..            | 12mo, | 2 00   |
| Kemp's Landscape Gardening.....  | 12mo, | 2 50   |
| Maynard's Landscape Gardening as Applied to Home Decora-<br>tion ..... | 12mo, | 1 50   |
| Stockbridge's Rocks and Soils.....                                     | 8vo,  | 2 50   |
| Woll's Handbook for Farmers and Dairymen.....                          | 16mo, | 1 50   |

## ARCHITECTURE.

|   |                |      |
|---|----------------|------|
| Baldwin's Steam Heating for Buildings.....                      | 12mo,          | 2 50 |
| Berg's Buildings and Structures of American Railroads....       | 4to,           | 5 00 |
| Birkmire's Planning and Construction of American Theatres.      | 8vo,           | 3 00 |
| “ Architectural Iron and Steel.....                             | 8vo,           | 3 50 |
| “ Compound Riveted Girders as Applied in Build-<br>ings .....   | 8vo,           | 2 00 |
| “ Planning and Construction of High Office Build-<br>ings ..... | 8vo,           | 3 50 |
| “ Skeleton Construction in Buildings.....                       | 8vo,           | 3 00 |
| Briggs's Modern American School Buildings.....                  | 8vo,           | 4 00 |
| Carpenter's Heating and Ventilating of Buildings.....           | 8vo,           | 3 00 |
| Freitag's Architectural Engineering.....                        | 8vo,           | 3 50 |
| “ Fireproofing of Steel Buildings.....                          | 8vo,           | 2 50 |
| Gerhard's Guide to Sanitary House-inspection.....               | 16mo,          | 1 00 |
| “ Theatre Fires and Panics.....                                 | 12mo,          | 1 50 |
| Hatfield's American House Carpenter.....                        | 8vo,           | 5 00 |
| Holly's Carpenters' and Joiners' Handbook.....                  | 18mo,          | 75   |
| Kidder's Architect's and Builder's Pocket-book..                | 16mo, morocco, | 4 00 |
| Merrill's Stones for Building and Decoration.....               | 8vo,           | 5 00 |

|  |            |      |
|--|------------|------|
| Monckton's Stair-building.....   | 4to,       | 4 00 |
| Patton's Practical Treatise on Foundations.....  | 8vo,       | 5 00 |
| Siebert and Biggin's Modern Stone-cutting and Masonry..  | 8vo,       | 1 50 |
| Wait's Engineering and Architectural Jurisprudence.....  | 8vo,       | 6 00 |
|  | Sheep,     | 6 50 |
| “ Law of Operations Preliminary to Construction in En-<br>gineering and Architecture.....  | 8vo,       | 5 00 |
|  | Sheep,     | 5 50 |
| “ Law of Contracts.....  | 8vo,       | 3 00 |
| Woodbury's Fire Protection of Mills.....   | 8vo,       | 2 50 |
| Worcester and Atkinson's Small Hospitals, Establishment and<br>Maintenance, and Suggestions for Hospital Architecture,<br>with Plans for a Small Hospital..... | 12mo,      | 1 25 |
| The World's Columbian Exposition of 1893.....  | Large 4to, | 1 00 |

### ARMY AND NAVY.

|  |                    |       |
|--|--------------------|-------|
| Bernadou's Smokeless Powder, Nitro-cellulose, and the Theory<br>of the Cellulose Molecule..... | 12mo,              | 2 50  |
| * Bruff's Text-book of Ordnance and Gunnery.....   | 8vo,               | 6 00  |
| Chase's Screw Propellers and Marine Propulsion.....  | 8vo,               | 3 00  |
| Craig's Azimuth.....   | 4to,               | 3 50  |
| Crehore and Squire's Polarizing Photo-chronograph.....   | 8vo,               | 3 00  |
| Cronkhite's Gunnery for Non-commissioned Officers..  | 24mo, mor.,        | 2 00  |
| * Davis's Elements of Law.....   | 8vo,               | 2 50  |
| * “ Treatise on the Military Law of United States...   | 8vo,               | 7 00  |
| *  | Sheep,             | 7 50  |
| De Brack's Cavalry Outpost Duties. (Carr.)....   | 24mo, morocco,     | 2 00  |
| Dietz's Soldier's First Aid Handbook.....  | 16mo, morocco,     | 1 25  |
| * Dredge's Modern French Artillery.....  | 4to, half morocco, | 15 00 |
| Durand's Resistance and Propulsion of Ships.....   | 8vo,               | 5 00  |
| * Dyer's Handbook of Light Artillery.....  | 12mo,              | 3 00  |
| Eissler's Modern High Explosives.....  | 8vo,               | 4 00  |
| * Fieberger's Text-book on Field Fortification.....  | Small 8vo,         | 2 00  |
| * Hoff's Elementary Naval Tactics.....   | 8vo,               | 1 50  |
| Ingalls's Handbook of Problems in Direct Fire.....   | 8vo,               | 4 00  |
| * “ Ballistic Tables.....  | 8vo,               | 1 50  |
| Lyons's Treatise on Electromagnetic Phenomena.....   | 8vo,               | 6 00  |
| * Mahan's Permanent Fortifications. (Mercur's.)  | 8vo, half mor.     | 7 50  |
| Manual for Courts-martial.....   | 16mo, morocco,     | 1 50  |
| * Mercur's Attack of Fortified Places.....   | 12mo,              | 2 00  |
| * “ Elements of the Art of War.....  | 8vo,               | 4 00  |
| Metcalf's Cost of Manufactures—And the Administration of<br>Workshops, Public and Private..... | 8vo,               | 5 00  |
| “ Ordnance and Gunnery.....  | 12mo,              | 5 00  |
| Murray's Infantry Drill Regulations.....   | 18mo, paper,       | 10    |
| * Phelps's Practical Marine Surveying.....   | 8vo,               | 2 50  |
| Powell's Army Officer's Examiner.....  | 12mo,              | 4 00  |

|   |                |      |
|---|----------------|------|
| Sharpe's Art of Subsisting Armies in War.....         | 18mo, morocco, | 1 50 |
| Walke's Lectures on Explosives.....                   | 8vo,           | 4 00 |
| * Wheeler's Siege Operations and Military Mining..... | 8vo,           | 2 00 |
| Winthrop's Abridgment of Military Law.....            | 12mo,          | 2 50 |
| Woodhull's Notes on Military Hygiene.....             | 16mo,          | 1 50 |
| Young's Simple Elements of Navigation.....            | 16mo, morocco, | 1 00 |
| Second Edition, Enlarged and Revised.....             | 16mo, mor.,    | 2 00 |

### ASSAYING.

|  |                |      |
|--|----------------|------|
| Fletcher's Practical Instructions in Quantitative Assaying with<br>the Blowpipe..... | 12mo, morocco, | 1 50 |
| Furman's Manual of Practical Assaying.....   | 8vo,           | 3 00 |
| Miller's Manual of Assaying.....   | 12mo,          | 1 00 |
| O'Driscoll's Notes on the Treatment of Gold Ores.....                                | 8vo,           | 2 00 |
| Ricketts and Miller's Notes on Assaying.....   | 8vo,           | 3 00 |
| Wilson's Cyanide Processes.....  | 12mo,          | 1 50 |
| " Chlorination Process .....   | 12mo,          | 1 50 |

### ASTRONOMY.

|   |       |      |
|---|-------|------|
| Craig's Azimuth.....  | 4to,  | 3 50 |
| Doolittle's Treatise on Practical Astronomy.....                      | 8vo,  | 4 00 |
| Gore's Elements of Geodesy.....                                       | 8vo,  | 2 50 |
| Hayford's Text-book of Geodetic Astronomy.....                        | 8vo,  | 3 00 |
| Merriman's Elements of Precise Surveying and Geodesy....              | 8vo,  | 2 50 |
| * Michie and Harlow's Practical Astronomy.....                        | 8vo,  | 3 00 |
| * White's Elements of Theoretical and Descriptive Astronomy.<br>..... | 12mo, | 2 00 |

### BOTANY.

|   |                |      |
|---|----------------|------|
| Baldwin's Orchids of New England.....   | Small 8vo,     | 1 50 |
| Davenport's Statistical Methods, with Special Reference to Bio-<br>logical Variation..... | 16mo, morocco, | 1 25 |
| Thomé and Bennett's Structural and Physiological Botany.<br>.....                         | 16mo,          | 2 25 |
| Westermaier's Compendium of General Botany. (Schneider.)                                  | 8vo,           | 2 00 |

### CHEMISTRY.

|  |       |      |
|--|-------|------|
| Adriance's Laboratory Calculations and Specific Gravity Tables,<br>.....                   | 12mo, | 1 25 |
| Allen's Tables for Iron Analysis.....  | 8vo,  | 3 00 |
| Arnold's Compendium of Chemistry. (Mandel.) ( <i>In preparation.</i> )                     |       |      |
| Austen's Notes for Chemical Students.....  | 12mo, | 1 50 |
| Bernadou's Smokeless Powder.—Nitro-cellulose, and Theory of<br>the Cellulose Molecule..... | 12mo, | 2 50 |
| Bolton's Quantitative Analysis.....  | 8vo,  | 1 50 |
| Brush and Penfield's Manual of Determinative Mineralogy..                                  | 8vo,  | 4 00 |
| Classen's Quantitative Chemical Analysis by Electrolysis. (Her-<br>rick—Boltwood.) .....   | 8vo,  | 3 00 |



|   |                            |      |
|---|----------------------------|------|
| Cohn's Indicators and Test-papers.....  | 12mo,                      | 2 00 |
| Craft's Short Course in Qualitative Chemical Analysis. (Schaeffer.) .....                       | 12mo,                      | 2 00 |
| Drechsel's Chemical Reactions. (Merrill.).....  | 12mo,                      | 1 25 |
| Eissler's Modern High Explosives.....   | 8vo,                       | 4 00 |
| Effront's Enzymes and their Applications. (Prescott.) ( <i>In preparation.</i> )                |                            |      |
| Erdmann's Introduction to Chemical Preparations. (Dunlap.)                                      | 12mo,                      | 1 25 |
| Fletcher's Practical Instructions in Quantitative Assaying with the Blowpipe.....               | 12mo, morocco,             | 1 50 |
| Fresenius's Manual of Qualitative Chemical Analysis. (Wells.)                                   | 8vo,                       | 5 00 |
| “ System of Instruction in Quantitative Chemical Analysis. (Allen.) .....                       | 8vo,                       | 6 00 |
| Fuertes's Water and Public Health.....  | 12mo,                      | 1 50 |
| Furman's Manual of Practical Assaying.....  | 8vo,                       | 3 00 |
| Gill's Gas and Fuel Analysis for Engineers.....   | 12mo,                      | 1 25 |
| Grotenfelt's Principles of Modern Dairy Practice. (Woll.)..                                     | 12mo,                      | 2 00 |
| Hammarsten's Text-book of Physiological Chemistry. (Mandel.)                                    | 8vo,                       | 4 00 |
| Helm's Principles of Mathematical Chemistry. (Morgan.)..  | 12mo,                      | 1 50 |
| Holleman's Text-book of Inorganic Chemistry. (Cooper.)  |                            |      |
|   | ( <i>In preparation.</i> ) |      |
| Hopkins's Oil-chemists' Handbook.....   | 8vo,                       | 3 00 |
| Keep's Cast Iron. ( <i>In preparation.</i> )  |                            |      |
| Ladd's Manual of Quantitative Chemical Analysis.....  | 12mo,                      | 1 00 |
| Landauer's Spectrum Analysis. (Tingle.).....  | 8vo,                       | 3 00 |
| Lassar-Cohn's Practical Urinary Analysis. (Lorenz.) ( <i>In preparation.</i> )                  |                            |      |
| Löb's Electrolysis and Electrosynthesis of Organic Compounds. (Lorenz.) .....                   | 12mo,                      | 1 00 |
| Mandel's Handbook for Bio-chemical Laboratory.....  | 12mo,                      | 1 50 |
| Mason's Water-supply. (Considered Principally from a Sanitary Standpoint.).....                 | 8vo,                       | 5 00 |
| “ Examination of Water. (Chemical and Bacteriological.) .....                                   | 12mo,                      | 1 25 |
| Meyer's Determination of Radicles in Carbon Compounds. (Tingle.) .....                          | 12mo,                      | 1 00 |
| Miller's Manual of Assaying.....  | 12mo,                      | 1 00 |
| Mixter's Elementary Text-book of Chemistry.....   | 12mo,                      | 1 50 |
| Morgan's Outline of Theory of Solution and its Results... ..                                    | 12mo,                      | 1 00 |
| “ Elements of Physical Chemistry.....   | 12mo,                      | 2 00 |
| Nichols's Water-supply. (Considered mainly from a Chemical and Sanitary Standpoint, 1883.)..... | 8vo,                       | 2 50 |
| O'Brine's Laboratory Guide in Chemical Analysis.....  | 8vo,                       | 2 00 |
| O'Driscoll's Notes on the Treatment of Gold Ores.....   | 8vo,                       | 2 00 |
| Ost and Kolbeck's Text-book of Chemical Technology. (Lorenz—Bozart.) ( <i>In preparation.</i> ) |                            |      |

|  |                |       |
|--|----------------|-------|
| * Penfield's Notes on Determinative Mineralogy and Record of Mineral Tests.....                    | 8vo, paper,    | 0 50  |
| Pinner's Introduction to Organic Chemistry. (Austen.)...   | 12mo,          | 1 50  |
| Poole's Calorific Power of Fuels.....  | 8vo,           | 3 00  |
| * Reising's Guide to Piece-dyeing.....   | 8vo,           | 25 00 |
| Richards and Woodman's Air, Water, and Food from a Sanitary Standpoint .....                       | 8vo,           | 2 00  |
| Richards's Cost of Living as Modified by Sanitary Science.   | 12mo,          | 1 00  |
| “ Cost of Food, a Study in Dieteries.....  | 12mo,          | 1 00  |
| Ricketts and Russell's Skeleton Notes upon Inorganic Chemistry. (Part I.—Non-metallic Elements.).. | 8vo, morocco,  | 75    |
| Ricketts and Miller's Notes on Assaying.....   | 8vo,           | 3 00  |
| Rideal's Sewage and the Bacterial Purification of Sewage..   | 8vo,           | 3 50  |
| Ruddiman's Incompatibilities in Prescriptions.....   | 8vo,           | 2 00  |
| Schimpf's Text-book of Volumetric Analysis.....  | 12mo,          | 2 50  |
| Spencer's Handbook for Chemists of Beet-sugar Houses.  | 16mo, morocco, | 3 00  |
| “ Handbook for Sugar Manufacturers and their Chemists .....  | 16mo, morocco, | 2 00  |
| Stockbridge's Rocks and Soils.....   | 8vo,           | 2 50  |
| * Tillman's Elementary Lessons in Heat.....  | 8vo,           | 1 50  |
| * “ Descriptive General Chemistry.....   | 8vo,           | 3 00  |
| Turneure and Russell's Public Water-supplies.....  | 8vo,           | 5 00  |
| Van Deventer's Physical Chemistry for Beginners. (Boltwood.)                                       | 12mo,          | 1 50  |
| Walke's Lectures on Explosives.....  | 8vo,           | 4 00  |
| Wells's Laboratory Guide in Qualitative Chemical Analysis.   | 8vo,           | 1 50  |
| “ Short Course in Inorganic Qualitative Chemical Analysis for Engineering Students.....            | 12mo,          | 1 50  |
| Whipple's Microscopy of Drinking-water.....  | 8vo,           | 3 50  |
| Wiechmann's Sugar Analysis.....  | Small 8vo,     | 2 50  |
| “ Lecture-notes on Theoretical Chemistry....   | 12mo,          | 3 00  |
| Wilson's Cyanide Processes.....  | 12mo,          | 1 50  |
| “ Chlorination Process.....  | 12mo,          | 1 50  |
| Wulling's Elementary Course in Inorganic Pharmaceutical and Medical Chemistry.....                 | 12mo,          | 2 00  |

## CIVIL ENGINEERING.

### BRIDGES AND ROOFS.    HYDRAULICS.    MATERIALS OF ENGINEERING.    RAILWAY ENGINEERING.

|   |                          |      |
|---|--------------------------|------|
| Baker's Engineers' Surveying Instruments.....         | 12mo,                    | 3 00 |
| Bixby's Graphical Computing Table....                 | Paper, 19½ x 24½ inches. | 25   |
| Davis's Elevation and Stadia Tables.....              | 8vo,                     | 1 00 |
| Folwell's Sewerage. (Designing and Maintenance.)..... | 8vo,                     | 3 00 |
| Freitag's Architectural Engineering.....              | 8vo,                     | 3 50 |

|  |                    |      |
|--|--------------------|------|
| Goodhue's Municipal Improvements.....                      | 12mo,              | 1 75 |
| Goodrich's Economic Disposal of Towns' Refuse.....         | 8vo,               | 3 50 |
| Gore's Elements of Geodesy.....                            | 8vo,               | 2 50 |
| Hayford's Text-book of Geodetic Astronomy.....             | 8vo,               | 3 00 |
| Howe's Retaining-walls for Earth.....                      | 12mo,              | 1 25 |
| Johnson's Theory and Practice of Surveying.....            | Small 8vo,         | 4 00 |
| "    Stadia and Earth-work Tables.....                     | 8vo,               | 1 25 |
| Kiersted's Sewage Disposal.....                            | 12mo,              | 1 25 |
| Mahan's Treatise on Civil Engineering. (1873.) (Wood.)..   | 8vo,               | 5 00 |
| * Mahan's Descriptive Geometry.....                        | 8vo,               | 1 50 |
| Merriman's Elements of Precise Surveying and Geodesy....   | 8vo,               | 2 50 |
| Merriman and Brooks's Handbook for Surveyors....           | 16mo, mor.,        | 2 00 |
| Merriman's Elements of Sanitary Engineering.....           | 8vo,               | 2 00 |
| Nugent's Plane Surveying. ( <i>In preparation.</i> )       |                    |      |
| Ogden's Sewer Design.....                                  | 12mo,              | 2 00 |
| Patton's Treatise on Civil Engineering.....                | 8vo, half leather, | 7 50 |
| Reed's Topographical Drawing and Sketching.....            | 4to,               | 5 00 |
| Rideal's Sewage and the Bacterial Purification of Sewage.. | 8vo,               | 3 50 |
| Siebert and Biggin's Modern Stone-cutting and Masonry..    | 8vo,               | 1 50 |
| Smith's Manual of Topographical Drawing. (McMillan.)..     | 8vo,               | 2 50 |
| * Trautwine's Civil Engineer's Pocket-book....             | 16mo, morocco,     | 5 00 |
| Wait's Engineering and Architectural Jurisprudence.....    | 8vo,               | 6 00 |
|  | Sheep,             | 6 50 |
| "    Law of Operations Preliminary to Construction in En-  |                    |      |
| gineering and Architecture.....                            | 8vo,               | 5 00 |
|  | Sheep,             | 5 50 |
| "    Law of Contracts.....                                 | 8vo,               | 3 00 |
| Warren's Stereotomy—Problems in Stone-cutting.....         | 8vo,               | 2 50 |
| Webb's Problems in the Use and Adjustment of Engineering   |                    |      |
| Instruments .....  | 16mo, morocco,     | 1 25 |
| * Wheeler's Elementary Course of Civil Engineering.....    | 8vo,               | 4 00 |
| Wilson's Topographic Surveying .....                       | 8vo,               | 3 50 |

## BRIDGES AND ROOFS.

|   |             |       |
|---|-------------|-------|
| Boller's Practical Treatise on the Construction of Iron Highway |             |       |
| Bridges .....   | 8vo,        | 2 00  |
| * Boller's Thames River Bridge.....                             | 4to, paper, | 5 00  |
| Burr's Course on the Stresses in Bridges and Roof Trusses,      |             |       |
| Arched Ribs, and Suspension Bridges.....                        | 8vo,        | 3 50  |
| Du Bois's Stresses in Framed Structures.....                    | Small 4to,  | 10 00 |
| Foster's Treatise on Wooden Trestle Bridges.....                | 4to,        | 5 00  |
| Fowler's Cofferdam Process for Piers.....                       | 8vo,        | 2 50  |
| Greene's Roof Trusses.....                                      | 8vo,        | 1 25  |
| "    Bridge Trusses.....  | 8vo,        | 2 50  |
| "    Arches in Wood, Iron, and Stone.....                       | 8vo,        | 2 50  |
| Howe's Treatise on Arches.....                                  | 8vo,        | 4 00  |



|  |             |       |
|--|-------------|-------|
| Johnson, Bryan and Turneure's Theory and Practice in the<br>Designing of Modern Framed Structures..... | Small 4to,  | 10 00 |
| Merriman and Jacoby's Text-book on Roofs and Bridges:  |             |       |
| Part I.—Stresses in Simple Trusses.....  | 8vo,        | 2 50  |
| Part II.—Graphic Statics.....  | 8vo,        | 2 00  |
| Part III.—Bridge Design. Fourth Ed. ( <i>In preparation.</i> )..                                       | 8vo,        | 2 50  |
| Part IV.—Higher Structures.....  | 8vo,        | 2 50  |
| Morison's Memphis Bridge.....  | 4to,        | 10 00 |
| Waddell's De Pontibus, a Pocket Book for Bridge Engineers.   |             |       |
|  | 16mo, mor., | 3 00  |
| “ Specifications for Steel Bridges.....  | 12mo,       | 1 25  |
| Wood's Treatise on the Theory of the Construction of Bridges<br>and Roofs .....                        | 8vo,        | 2 00  |
| Wright's Designing of Draw-spans:  |             |       |
| Part I.—Plate-girder Draws.....  | 8vo,        | 2 50  |
| Part II.—Riveted-truss and Pin-connected Long-span Draws.  |             |       |
|  | 8vo,        | 2 50  |
| Two parts in one volume.....   | 8vo,        | 3 50  |

### HYDRAULICS.

|  |             |       |
|--|-------------|-------|
| Bazin's Experiments upon the Contraction of the Liquid Vein<br>Issuing from an Orifice. (Trautwine.).....                                | 8vo,        | 2 00  |
| Bovey's Treatise on Hydraulics.....  | 8vo,        | 5 00  |
| Church's Mechanics of Engineering.....   | 8vo,        | 6 00  |
| Coffin's Graphical Solution of Hydraulic Problems..  | 16mo, mor., | 2 50  |
| Flather's Dynamometers, and the Measurement of Power.  | 12mo,       | 3 00  |
| Folwell's Water-supply Engineering.....  | 8vo,        | 4 00  |
| Frizell's Water-power.....   | 8vo,        | 5 00  |
| Fuertes's Water and Public Health.....   | 12mo,       | 1 50  |
| “ Water-filtration Works.....  | 12mo,       | 2 50  |
| Ganguillet and Kutter's General Formula for the Uniform<br>Flow of Water in Rivers and Other Channels. (Her-<br>ing and Trautwine.)..... | 8vo,        | 4 00  |
| Hazen's Filtration of Public Water-supply.....   | 8vo,        | 3 00  |
| Hazleurst's Towers and Tanks for Water-works.....  | 8vo,        | 2 50  |
| Herschel's 115 Experiments on the Carrying Capacity of Large,<br>Riveted, Metal Conduits.....  | 8vo,        | 2 00  |
| Mason's Water-supply. (Considered Principally from a Sani-<br>tary Standpoint.).....   | 8vo,        | 5 00  |
| Merriman's Treatise on Hydraulics.....   | 8vo,        | 4 00  |
| * Michie's Elements of Analytical Mechanics.....   | 8vo,        | 4 00  |
| Schuyler's Reservoirs for Irrigation, Water-power, and Domestic<br>Water-supply.....   | Large 8vo,  | 5 00  |
| Turneure and Russell. Public Water-supplies.....   | 8vo,        | 5 00  |
| Wegmann's Design and Construction of Dams.....   | 4to,        | 5 00  |
| “ Water-supply of the City of New York from 1658 to<br>1895 .....  | 4to,        | 10 00 |
| Weisbach's Hydraulics and Hydraulic Motors. (Du Bois.)..   | 8vo,        | 5 00  |
| Wilson's Manual of Irrigation Engineering.....   | Small 8vo,  | 4 00  |
| Wolff's Windmill as a Prime Mover.....   | 8vo,        | 3 00  |
| Wood's Turbines.....   | 8vo,        | 2 50  |
| “ Elements of Analytical Mechanics.....  | 8vo,        | 3 00  |

### MATERIALS OF ENGINEERING.

|  |             |      |
|--|-------------|------|
| Baker's Treatise on Masonry Construction.....              | 8vo,        | 5 00 |
| Black's United States Public Works.....                    | Oblong 4to, | 5 00 |
| Bovey's Strength of Materials and Theory of Structures.... | 8vo,        | 7 50 |

|  |                |       |
|--|----------------|-------|
| Burr's Elasticity and Resistance of the Materials of Engineering .....                             | 8vo,           | 5 00  |
| Byrne's Highway Construction.....  | 8vo,           | 5 00  |
| "    Inspection of the Materials and Workmanship Employed in Construction.....                     | 16mo,          | 3 00  |
| Church's Mechanics of Engineering.....   | 8vo,           | 6 00  |
| Du Bois's Mechanics of Engineering. Vol. I.....  | Small 4to,     | 10 00 |
| Johnson's Materials of Construction.....   | Large 8vo,     | 6 00  |
| Keep's Cast Iron. ( <i>In preparation.</i> )   |                |       |
| Lanza's Applied Mechanics.....   | 8vo,           | 7 50  |
| Martens's Handbook on Testing Materials. (Henning.).....   | 2 vols., 8vo,  | 7 50  |
| Merrill's Stones for Building and Decoration.....  | 8vo,           | 5 00  |
| Merriman's Text-book on the Mechanics of Materials.....  | 8vo,           | 4 00  |
| Merriman's Strength of Materials.....  | 12mo,          | 1 00  |
| Metcalf's Steel. A Manual for Steel-users.....   | 12mo,          | 2 00  |
| Patton's Practical Treatise on Foundations.....  | 8vo,           | 5 00  |
| Rockwell's Roads and Pavements in France.....  | 12mo,          | 1 25  |
| Smith's Wire: Its Use and Manufacture.....   | Small 4to,     | 3 00  |
| Spalding's Hydraulic Cement.....   | 12mo,          | 2 00  |
| "    Text-book on Roads and Pavements.....   | 12mo,          | 2 00  |
| Thurston's Materials of Engineering.....   | 3 Parts, 8vo,  | 8 00  |
| Part I.—Non-metallic Materials of Engineering and Metallurgy .....                                 | 8vo,           | 2 00  |
| Part II.—Iron and Steel.....   | 8vo,           | 3 50  |
| Part III.—A Treatise on Brasses, Bronzes and Other Alloys and Their Constituents.....              | 8vo,           | 2 50  |
| Thurston's Text-book of the Materials of Construction.....   | 8vo,           | 5 00  |
| Tillson's Street Pavements and Paving Materials.....   | 8vo,           | 4 00  |
| Waddell's De Pontibus. (A Pocket-book for Bridge Engineers.)                                       | 16mo, morocco, | 3 00  |
| "    Specifications for Steel Bridges.....   | 12mo,          | 1 25  |
| Wood's Treatise on the Resistance of Materials, and an Appendix on the Preservation of Timber..... | 8vo,           | 2 00  |
| "    Elements of Analytical Mechanics.....   | 8vo,           | 3 00  |

## RAILWAY ENGINEERING.

|  |                    |       |
|--|--------------------|-------|
| Berg's Buildings and Structures of American Railroads..                                | 4to,               | 5 00  |
| Brooks's Handbook of Street Railroad Location..  | 16mo, morocco,     | 1 50  |
| Butts's Civil Engineer's Field-book.....   | 16mo, morocco,     | 2 50  |
| Crandall's Transition Curve.....   | 16mo, morocco,     | 1 50  |
| "    Railway and Other Earthwork Tables.....   | 8vo,               | 1 50  |
| Dawson's Electric Railways and Tramways.Small 4to, half mor.,                          |                    | 12 50 |
| "    "Engineering" and Electric Traction Pocket-book.                                  | 16mo, morocco,     | 4 00  |
| Dredge's History of the Pennsylvania Railroad: (1879.) Paper,                          |                    | 5 00  |
| * Drinker's Tunneling, Explosive Compounds, and Rock Drills.                           | 4to, half morocco, | 25 00 |
| Fisher's Table of Cubic Yards.....   | Cardboard,         | 25    |
| Godwin's Railroad Engineers' Field-book and Explorers' Guide.                          | 16mo, morocco,     | 2 50  |
| Howard's Transition Curve Field-book.....  | 16mo, morocco,     | 1 50  |
| Hudson's Tables for Calculating the Cubic Contents of Excavations and Embankments..... | 8vo,               | 1 00  |
| Nagle's Field Manual for Railroad Engineers....  | 16mo, morocco,     | 3 00  |
| Philbrick's Field Manual for Engineers.....  | 16mo, morocco,     | 3 00  |
| Pratt and Alden's Street-railway Road-bed.....   | 8vo,               | 2 00  |



|  |                |      |
|--|----------------|------|
| Searles's Field Engineering.....   | 16mo, morocco, | 3 00 |
| “ Railroad Spiral.....   | 16mo, morocco, | 1 50 |
| Taylor's Prismoïdal Formulæ and Earthwork.....   | 8vo,           | 1 50 |
| * Trautwine's Method of Calculating the Cubic Contents of Excavations and Embankments by the Aid of Diagrams ..... | 8vo,           | 2 00 |
| * “ The Field Practice of Laying Out Circular Curves for Railroads.....  | 12mo, morocco, | 2 50 |
| * “ Cross-section Sheet.....   | Paper,         | 25   |
| Webb's Railroad Construction.....  | 8vo,           | 4 00 |
| Wellington's Economic Theory of the Location of Railways..   | Small 8vo,     | 5 00 |

## DRAWING.

|  |            |      |
|--|------------|------|
| Barr's Kinematics of Machinery.....  | 8vo,       | 2 50 |
| * Bartlett's Mechanical Drawing.....   | 8vo,       | 3 00 |
| Durley's Elementary Text-book of the Kinematics of Machines.<br>( <i>In preparation.</i> ) |            |      |
| Hill's Text-book on Shades and Shadows, and Perspective..                                  | 8vo,       | 2 00 |
| Jones's Machine Design:  |            |      |
| Part I.—Kinematics of Machinery.....   | 8vo,       | 1 50 |
| Part II.—Form, Strength and Proportions of Parts.....                                      | 8vo,       | 3 00 |
| MacCord's Elements of Descriptive Geometry.....  | 8vo,       | 3 00 |
| “ Kinematics; or, Practical Mechanism.....   | 8vo,       | 5 00 |
| “ Mechanical Drawing.....  | 4to,       | 4 00 |
| “ Velocity Diagrams.....   | 8vo,       | 1 50 |
| * Mahan's Descriptive Geometry and Stone-cutting.....                                      | 8vo,       | 1 50 |
| Mahan's Industrial Drawing. (Thompson.).....   | 8vo,       | 3 50 |
| Reed's Topographical Drawing and Sketching.....  | 4to,       | 5 00 |
| Rcid's Course in Mechanical Drawing.....   | 8vo,       | 2 00 |
| “ Text-book of Mechanical Drawing and Elementary Machine Design.....                       | 8vo,       | 3 00 |
| Robinson's Principles of Mechanism.....  | 8vo,       | 3 00 |
| Smith's Manual of Topographical Drawing. (McMillan.)                                       | 8vo,       | 2 50 |
| Warren's Elements of Plane and Solid Free-hand Geometrical Drawing .....                   | 12mo,      | 1 00 |
| “ Drafting Instruments and Operations.....   | 12mo,      | 1 25 |
| “ Manual of Elementary Projection Drawing....  | 12mo,      | 1 50 |
| “ Manual of Elementary Problems in the Linear Perspective of Form and Shadow.....          | 12mo,      | 1 00 |
| “ Plane Problems in Elementary Geometry.....   | 12mo,      | 1 25 |
| “ Primary Geometry.....  | 12mo,      | 75   |
| “ Elements of Descriptive Geometry, Shades, and Perspective .....                          | 8vo,       | 3 50 |
| “ General Problems of Shades and Shadows.....  | 8vo,       | 3 00 |
| “ Elements of Machine Construction and Drawing..   | 8vo,       | 7 50 |
| “ Problems, Theorems, and Examples in Descriptive Geometry .....                           | 8vo,       | 2 50 |
| Weisbach's Kinematics and the Power of Transmission. (Herrmann and Klein.) .....           | 8vo,       | 5 00 |
| Whelpley's Practical Instruction in the Art of Letter Engraving .....                      | 12mo,      | 2 00 |
| Wilson's Topographic Surveying.....  | 8vo,       | 3 50 |
| Wilson's Free-hand Perspective.....  | 8vo,       | 2 50 |
| Woolf's Elementary Course in Descriptive Geometry..  | Large 8vo, | 3 00 |





|  |                |       |
|--|----------------|-------|
| Ford's Boiler Making for Boiler Makers.....  | 18mo,          | 1 00  |
| Hopkins's Oil-chemists' Handbook.....  | 8vo,           | 3 00  |
| Keep's Cast Iron. ( <i>In preparation.</i> )   |                |       |
| Metcalf's Steel. A Manual for Steel-users.....   | 12mo,          | 2 00  |
| Metcalf's Cost of Manufactures—And the Administration of<br>Workshops, Public and Private..... | 8vo,           | 5 00  |
| Meyer's Modern Locomotive Construction.....  | 4to,           | 10 00 |
| * Reising's Guide to Piece-dyeing.....   | 8vo,           | 25 00 |
| Smith's Press-working of Metals.....   | 8vo,           | 3 00  |
| “ Wire: Its Use and Manufacture.....   | Small 4to,     | 3 00  |
| Spalding's Hydraulic Cement.....   | 12mo,          | 2 00  |
| Spencer's Handbook for Chemists of Beet-sugar Houses.<br>16mo, morocco,                        |                | 3 00  |
| “ Handbook for Sugar Manufacturers and their Chem-<br>ists.....                                | 16mo, morocco, | 2 00  |
| Thurston's Manual of Steam-boilers, their Designs, Construc-<br>tion and Operation.....        | 8vo,           | 5 00  |
| Walke's Lectures on Explosives.....  | 8vo,           | 4 00  |
| West's American Foundry Practice.....  | 12mo,          | 2 50  |
| “ Moulder's Text-book.....   | 12mo,          | 2 50  |
| Wiechmann's Sugar Analysis.....  | Small 8vo,     | 2 50  |
| Wolff's Windmill as a Prime Mover.....   | 8vo,           | 3 00  |
| Woodbury's Fire Protection of Mills.....   | 8vo,           | 2 50  |

## MATHEMATICS.

|  |            |            |
|--|------------|------------|
| Baker's Elliptic Functions.....  | 8vo,       | 1 50       |
| * Bass's Elements of Differential Calculus.....  | 12mo,      | 4 00       |
| Briggs's Elements of Plane Analytic Geometry.....                                      | 12mo,      | 1 00       |
| Chapman's Elementary Course in Theory of Equations...                                  | 12mo,      | 1 50       |
| Compton's Manual of Logarithmic Computations.....                                      | 12mo,      | 1 50       |
| Davis's Introduction to the Logic of Algebra.....                                      | 8vo,       | 1 50       |
| Halsted's Elements of Geometry.....  | 8vo,       | 1 75       |
| “ Elementary Synthetic Geometry.....   | 8vo,       | 1 50       |
| Johnson's Three-place Logarithmic Tables: Vest-pocket size, pap.,<br>100 copies for    |            | 15<br>5 00 |
| Mounted on heavy cardboard, 8 × 10 inches,<br>10 copies for                            |            | 25<br>2 00 |
| “ Elementary Treatise on the Integral Calculus.<br>Small 8vo,                          |            | 1 50       |
| “ Curve Tracing in Cartesian Co-ordinates.....   | 12mo,      | 1 00       |
| “ Treatise on Ordinary and Partial Differential<br>Equations.....                      | Small 8vo, | 3 50       |
| “ Theory of Errors and the Method of Least<br>Squares.....                             | 12mo,      | 1 50       |
| * “ Theoretical Mechanics.....   | 12mo,      | 3 00       |
| * Ludlow and Bass. Elements of Trigonometry and Logarith-<br>mic and Other Tables..... | 8vo,       | 3 00       |
| “ Trigonometry. Tables published separately..  | Each,      | 2 00       |
| Merriman and Woodward. Higher Mathematics.....   | 8vo,       | 5 00       |
| Merriman's Method of Least Squares.....  | 8vo,       | 2 00       |
| Rice and Johnson's Elementary Treatise on the Differential<br>Calculus.....            | Small 8vo, | 3 00       |
| “ Differential and Integral Calculus. 2 vols.<br>in one.....                           | Small 8vo, | 2 50       |
| Wood's Elements of Co-ordinate Geometry.....   | 8vo,       | 2 00       |
| “ Trigonometry: Analytical, Plane, and Spherical....                                   | 12mo,      | 1 00       |





|  |               |      |
|--|---------------|------|
| Metcalf's Steel. A Manual for Steel-users.....   | 12mo,         | 2 00 |
| Smith's Wire: Its Use and Manufacture.....   | Small 4to,    | 3 00 |
| Thurston's Materials of Engineering.....   | 3 vols., 8vo, | 8 00 |
| Part II.—Iron and Steel.....   | 8vo,          | 3 50 |
| Part III.—A Treatise on Brasses, Bronzes and Other Alloys<br>and their Constituents.....               | 8vo,          | 2 50 |
| Thurston's Text-book of the Materials of Construction....  | 8vo,          | 5 00 |
| Wood's Treatise on the Resistance of Materials and an Ap-<br>pendix on the Preservation of Timber..... | 8vo,          | 2 00 |
| " Elements of Analytical Mechanics.....  | 8vo,          | 3 00 |

## STEAM ENGINES AND BOILERS.

|   |                |       |
|---|----------------|-------|
| Carnot's Reflections on the Motive Power of Heat. (Thurston.)   | 12mo,          | 1 50  |
| Dawson's "Engineering" and Electric Traction Pocket-book.   | 16mo, morocco, | 4 00  |
| Ford's Boiler Making for Boiler Makers.....   | 18mo,          | 1 00  |
| Hemenway's Indicator Practice and Steam-engine Economy.   | 12mo,          | 2 00  |
| Hutton's Mechanical Engineering of Power Plants.....  | 8vo,           | 5 00  |
| " Heat and Heat-engines.....  | 8vo,           | 5 00  |
| Kent's Steam-boiler Economy.....  | 8vo,           | 4 00  |
| Kneass's Practice and Theory of the Injector.....   | 8vo,           | 1 50  |
| MacCord's Slide-valves.....   | 8vo,           | 2 00  |
| Meyer's Modern Locomotive Construction.....   | 4to,           | 10 00 |
| Peabody's Manual of the Steam-engine Indicator.....   | 12mo,          | 1 50  |
| " Tables of the Properties of Saturated Steam and<br>Other Vapors.....                                    | 8vo,           | 1 00  |
| " Thermodynamics of the Steam-engine and Other<br>Heat-engines .....                                      | 8vo,           | 5 00  |
| " Valve-gears for Steam-engines.....  | 8vo,           | 2 50  |
| Peabody and Miller. Steam-boilers.....  | 8vo,           | 4 00  |
| Pray's Twenty Years with the Indicator.....   | Large 8vo,     | 2 50  |
| Pupin's Thermodynamics of Reversible Cycles in Gases and<br>Saturated Vapors. (Osterberg.).....           | 12mo,          | 1 25  |
| Reagan's Locomotive Mechanism and Engineering.....  | 12mo,          | 2 00  |
| Rontgen's Principles of Thermodynamics. (Du Bois.)....  | 8vo,           | 5 00  |
| Sinclair's Locomotive Engine Running and Management..   | 12mo,          | 2 00  |
| Smart's Handbook of Engineering Laboratory Practice..   | 12mo,          | 2 50  |
| Snow's Steam-boiler Practice.....   | 8vo,           | 3 00  |
| Spangler's Valve-gears.....   | 8vo,           | 2 50  |
| " Notes on Thermodynamics.....  | 12mo,          | 1 00  |
| Thurston's Handy Tables.....  | 8vo,           | 1 50  |
| " Manual of the Steam-engine.....   | 2 vols., 8vo,  | 10 00 |
| Part I.—History, Structure, and Theory.....   | 8vo,           | 6 00  |
| Part II.—Design, Construction, and Operation.....   | 8vo,           | 6 00  |
| Thurston's Handbook of Engine and Boiler Trials, and the Use<br>of the Indicator and the Prony Brake..... | 8vo,           | 5 00  |
| " Stationary Steam-engines.....   | 8vo,           | 2 50  |
| " Steam-boiler Explosions in Theory and in Prac-<br>tice .....  | 12mo,          | 1 50  |
| " Manual of Steam-boilers, Their Designs, Construc-<br>tion, and Operation.....                           | 8vo,           | 5 00  |
| Weisbach's Heat, Steam, and Steam-engines. (Du Bois.)..   | 8vo,           | 5 00  |
| Whitham's Steam-engine Design.....  | 8vo,           | 5 00  |
| Wilson's Treatise on Steam-boilers. (Flather.).....   | 16mo,          | 2 50  |
| Wood's Thermodynamics, Heat Motors, and Refrigerating<br>Machines .....                                   | 8vo,           | 4 00  |

## MECHANICS AND MACHINERY.

|   |                 |       |
|---|-----------------|-------|
| Barr's Kinematics of Machinery.....   | 8vo,            | 2 50  |
| Bovey's Strength of Materials and Theory of Structures..  | 8vo,            | 7 50  |
| Chordal.—Extracts from Letters.....   | 12mo,           | 2 00  |
| Church's Mechanics of Engineering.....  | 8vo,            | 6 00  |
| "    Notes and Examples in Mechanics.....   | 8vo,            | 2 00  |
| Compton's First Lessons in Metal-working.....   | 12mo,           | 1 50  |
| Compton and De Grootd. The Speed Lathe.....   | 12mo,           | 1 50  |
| Cromwell's Treatise on Toothed Gearing.....   | 12mo,           | 1 50  |
| "    Treatise on Belts and Pulleys.....   | 12mo,           | 1 50  |
| Dana's Text-book of Elementary Mechanics for the Use of<br>Colleges and Schools.....                        | 12mo,           | 1 50  |
| Dingey's Machinery Pattern Making.....  | 12mo,           | 2 00  |
| Dredge's Record of the Transportation Exhibits Building of the<br>World's Columbian Exposition of 1893..... | 4to, half mor., | 5 00  |
| Du Bois's Elementary Principles of Mechanics:   |                 |       |
| Vol. I.—Kinematics .....  | 8vo,            | 3 50  |
| Vol. II.—Statics.....   | 8vo,            | 4 00  |
| Vol. III.—Kinetics.....   | 8vo,            | 3 50  |
| Du Bois's Mechanics of Engineering. Vol. I.....   | Small 4to,      | 10 00 |
| Durley's Elementary Text-book of the Kinematics of Machines.<br>(In preparation.)                           |                 |       |
| Fitzgerald's Boston Machinist.....  | 16mo,           | 1 00  |
| Flather's Dynamometers, and the Measurement of Power..  | 12mo,           | 3 00  |
| "    Rope Driving.....  | 12mo,           | 2 00  |
| Hall's Car Lubrication.....   | 12mo,           | 1 00  |
| Holly's Art of Saw Filing.....  | 18mo,           | 75    |
| * Johnson's Theoretical Mechanics.....  | 12mo,           | 3 00  |
| Jones's Machine Design:   |                 |       |
| Part I.—Kinematics of Machinery.....  | 8vo,            | 1 50  |
| Part II.—Form, Strength and Proportions of Parts....  | 8vo,            | 3 00  |
| Kerr's Power and Power Transmission. (In preparation.)  |                 |       |
| Lanza's Applied Mechanics.....  | 8vo,            | 7 50  |
| MacCord's Kinematics; or, Practical Mechanism.....  | 8vo,            | 5 00  |
| "    Velocity Diagrams.....   | 8vo,            | 1 50  |
| Merriman's Text-book on the Mechanics of Materials.....   | 8vo,            | 4 00  |
| * Michie's Elements of Analytical Mechanics.....  | 8vo,            | 4 00  |
| Reagan's Locomotive Mechanism and Engineering.....  | 12mo,           | 2 00  |
| Reid's Course in Mechanical Drawing.....  | 8vo,            | 2 00  |
| "    Text-book of Mechanical Drawing and Elementary<br>Machine Design.....                                  | 8vo,            | 3 00  |
| Richards's Compressed Air.....  | 12mo,           | 1 50  |
| Robinson's Principles of Mechanism.....   | 8vo,            | 3 00  |
| Sinclair's Locomotive-engine Running and Management..   | 12mo,           | 2 00  |
| Smith's Press-working of Metals.....  | 8vo,            | 3 00  |
| Thurston's Treatise on Friction and Lost Work in Machin-<br>ery and Mill Work.....                          | 8vo,            | 3 00  |
| "    Animal as a Machine and Prime Motor, and the<br>Laws of Energetics.....                                | 12mo,           | 1 00  |
| Warren's Elements of Machine Construction and Drawing. .  | 8vo,            | 7 50  |
| Weisbach's Kinematics and the Power of Transmission.<br>(Herrman—Klein.) .....                              | 8vo,            | 5 00  |
| "    Machinery of Transmission and Governors. (Herr-<br>man—Klein.) .....                                   | 8vo,            | 5 00  |
| Wood's Elements of Analytical Mechanics.....  | 8vo,            | 3 00  |
| "    Principles of Elementary Mechanics.....  | 12mo,           | 1 25  |
| "    Turbines .....   | 8vo,            | 2 50  |
| The World's Columbian Exposition of 1893.....   | 4to,            | 1 00  |



## METALLURGY.

|  |            |
|--|------------|
| Egleston's Metallurgy of Silver, Gold, and Mercury:                                      |            |
| Vol. I.—Silver.....  | 8vo, 7 50  |
| Vol. II.—Gold and Mercury.....   | 8vo, 7 50  |
| Keep's Cast Iron. ( <i>In preparation.</i> )   |            |
| Kunhardt's Practice of Ore Dressing in Europe.....                                       | 8vo, 1 50  |
| Le Chatelier's High-temperature Measurements. (Boudouard—<br>Burgess.) .....             | 12mo, 3 00 |
| Metcalf's Steel. A Manual for Steel-users.....   | 12mo, 2 00 |
| Thurston's Materials of Engineering. In Three Parts.....                                 | 8vo, 8 00  |
| Part II.—Iron and Steel.....   | 8vo, 3 50  |
| Part III.—A Treatise on Brasses, Bronzes and Other Alloys<br>and Their Constituents..... | 8vo, 2 50  |

## MINERALOGY.

|  |                                |
|--|--------------------------------|
| Barringer's Description of Minerals of Commercial Value.                                 | Oblong, morocco, 2 50          |
| Boyd's Resources of Southwest Virginia.....  | 8vo, 3 00                      |
| " Map of Southwest Virginia.....   | Pocket-book form, 2 00         |
| Brush's Manual of Determinative Mineralogy. (Penfield.)                                  | 8vo, 4 00                      |
| Chester's Catalogue of Minerals.....   | 8vo, paper, 1 00               |
|  | Cloth, 1 25                    |
| " Dictionary of the Names of Minerals.....   | 8vo, 3 50                      |
| Dana's System of Mineralogy.....   | Large 8vo, half leather, 12 50 |
| " First Appendix to Dana's New "System of Mineralogy."                                   | Large 8vo, 1 00                |
| " Text-book of Mineralogy.....   | 8vo, 4 00                      |
| " Minerals and How to Study Them.....  | 12mo, 1 50                     |
| " Catalogue of American Localities of Minerals.  | Large 8vo, 1 00                |
| " Manual of Mineralogy and Petrography.....  | 12mo, 2 00                     |
| Egleston's Catalogue of Minerals and Synonyms.....                                       | 8vo, 2 50                      |
| Hussak's The Determination of Rock-forming Minerals.<br>(Smith.) .....                   | Small 8vo, 2 00                |
| * Penfield's Notes on Determinative Mineralogy and Record of<br>Mineral Tests.....       | 8vo, paper, 50                 |
| Rosenbusch's Microscopical Physiography of the Rock-making<br>Minerals. (Idding's.)..... | 8vo, 5 00                      |
| * Tillman's Text-book of Important Minerals and Rocks..                                  | 8vo, 2 00                      |
| Williams's Manual of Lithology.....  | 8vo, 3 00                      |

## MINING.

|  |                          |
|--|--------------------------|
| Beard's Ventilation of Mines.....  | 12mo, 2 50               |
| Boyd's Resources of Southwest Virginia.....                              | 8vo, 3 00                |
| " Map of Southwest Virginia.....   | Pocket-book form, 2 00   |
| * Drinker's Tunneling, Explosive Compounds, and Rock<br>Drills.....      | 4to, half morocco, 25 00 |
| Eissler's Modern High Explosives.....                                    | 8vo, 4 00                |
| Goodyear's Coal-mines of the Western Coast of the United<br>States ..... | 12mo, 2 50               |
| Ihlseng's Manual of Mining.....  | 8vo, 4 00                |
| Kunhardt's Practice of Ore Dressing in Europe.....                       | 8vo, 1 50                |
| O'Driscoll's Notes on the Treatment of Gold Ores.....                    | 8vo, 2 00                |
| Sawyer's Accidents in Mines.....   | 8vo, 7 00                |
| Walke's Lectures on Explosives.....                                      | 8vo, 4 00                |
| Wilson's Cyanide Processes.....  | 12mo, 1 50               |
| Wilson's Chlorination Process.....                                       | 12mo, 1 50               |

|   |       |      |
|---|-------|------|
| Wilson's Hydraulic and Placer Mining.....                             | 12mo, | 2 00 |
| Wilson's Treatise on Practical and Theoretical Mine Ventilation ..... | 12mo, | 1 25 |

### SANITARY SCIENCE.

|  |       |      |
|--|-------|------|
| Folwell's Sewerage. (Designing, Construction and Maintenance.)                                     |       |      |
|  | 8vo,  | 3 00 |
| "    Water-supply Engineering.....   | 8vo,  | 4 00 |
| Fuertes's Water and Public Health.....   | 12mo, | 1 50 |
| "    Water-filtration Works.....   | 12mo, | 2 50 |
| Gerhard's Guide to Sanitary House-inspection.....  | 16mo, | 1 00 |
| Goodrich's Economical Disposal of Towns' Refuse... Demy  | 8vo,  | 3 50 |
| Hazen's Filtration of Public Water-supplies.....   | 8vo,  | 3 00 |
| Kiersted's Sewage Disposal.....  | 12mo, | 1 25 |
| Mason's Water-supply. (Considered Principally from a Sanitary Standpoint.....)                     | 8vo,  | 5 00 |
| "    Examination of Water. (Chemical and Bacteriological.) .....                                   | 12mo, | 1 25 |
| Merriman's Elements of Sanitary Engineering.....   | 8vo,  | 2 00 |
| Nichols's Water-supply. (Considered Mainly from a Chemical and Sanitary Standpoint.) (1883.) ..... | 8vo,  | 2 50 |
| Ogden's Sewer Design.....  | 12mo, | 2 00 |
| Richards's Cost of Food. A Study in Dietaries.....   | 12mo, | 1 00 |
| Richards and Woodman's Air, Water, and Food from a Sanitary Standpoint.....                        | 8vo,  | 2 00 |
| Richards's Cost of Living as Modified by Sanitary Science.   | 12mo, | 1 00 |
| Rideal's Sewage and Bacterial Purification of Sewage.....  | 8vo,  | 3 50 |
| Turneure and Russell's Public Water-supplies.....  | 8vo,  | 5 00 |
| Whipple's Microscopy of Drinking-water.....  | 8vo,  | 3 50 |
| Woodhull's Notes on Military Hygiene.....  | 16mo, | 1 50 |

### MISCELLANEOUS.

|   |                |      |
|---|----------------|------|
| Barker's Deep-sea Soundings.....  | 8vo,           | 2 00 |
| Emmons's Geological Guide-book of the Rocky Mountain Excursion of the International Congress of Geologists.   |                |      |
|   | Large 8vo,     | 1 50 |
| Ferrel's Popular Treatise on the Winds.....   | 8vo,           | 4 00 |
| Haines's American Railway Management.....   | 12mo,          | 2 50 |
| Mott's Composition, Digestibility, and Nutritive Value of Food.   |                |      |
|   | Mounted chart, | 1 25 |
| "    Fallacy of the Present Theory of Sound.....  | 16mo,          | 1 00 |
| Ricketts's History of Rensselaer Polytechnic Institute, 1824-1894.....  | Small 8vo,     | 3 00 |
| Rotherham's Emphasised New Testament.....   | Large 8vo,     | 2 00 |
| "    Critical Emphasised New Testament.....   | 12mo,          | 1 50 |
| Steel's Treatise on the Diseases of the Dog.....  | 8vo,           | 3 50 |
| Totten's Important Question in Metrology.....   | 8vo,           | 2 50 |
| The World's Columbian Exposition of 1893.....   | 4to,           | 1 00 |
| Worcester and Atkinson. Small Hospitals, Establishment and Maintenance, and Suggestions for Hospital Architecture, with Plans for a Small Hospital..... | 12mo,          | 1 25 |

### HEBREW AND CHALDEE TEXT-BOOKS.

|  |                          |      |
|--|--------------------------|------|
| Green's Grammar of the Hebrew Language.....  | 8vo,                     | 3 00 |
| "    Elementary Hebrew Grammar.....  | 12mo,                    | 1 25 |
| "    Hebrew Chrestomathy.....  | 8vo,                     | 2 00 |
| Gesenius's Hebrew and Chaldee Lexicon to the Old Testament Scriptures. (Tregelles.)..... | Small 4to, half morocco, | 5 00 |
| Letteris's Hebrew Bible.....   | 8vo,                     | 2 25 |

MAR 26 1902



MAR 26 1902

LIBRARY OF THE  
MUSEUM OF NATURAL HISTORY  
MAR 26 1902

U.S. GEOLOGICAL SURVEY









LIBRARY OF CONGRESS



0 002 969 011 A